

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

TWINBIZ RENTAL PTE LTD
2 KAKI BUKIT AVE 2 #01-18 KAKI BUKIT
AUTOHUB
SINGAPORE 417921

Contact : 91509303

TP Chime
Celine

TAX INVOICE

Repair Code : CLM17273

Date in : 02/07/2022

Vehicle Num. : SLS5264E

Model : TOYOTA PRIUS ALPHA 1.8S CVT

Chassis/Eng# : ZVW400026228/2ZR1990506

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>behind</i>	1	556.40	✓ 556.40
REAR BUMPER END SEAL COVER L/R <i>behind</i>	2	92.30	✓ 184.60
REAR BUMPER REFLECTOR L/R <i>cracked</i>	2	58.00	✓ 116.00
REAR BUMPER SIDE RTAINER L/R <i>cracked</i>	2	142.80	180 ✓ 285.60
REAR COMPARTMENT TRAY <i>behind</i>	1	679.30	485 ✓ 679.30
REAR COMPARTMENT TRAY TOP COVER <i>behind</i>	1	562.50	380 ✓ 562.50
REAR DECK BOX TOP COVER L/R <i>new</i>	2	381.10	+ 762.20
REAR END PANEL <i>Dented</i>	1	687.30	✓ 687.30
REAR END PANEL ANTENNA SENSOR <i>cracked</i>	1	485.00	165 ✓ 485.00
REAR END PANEL INNER TOP GARNISH <i>behind</i>	1	287.90	✓ 287.90
REAR FENDER INNER UPHOLSTERY TRIM GARNISH L/R <i>cracked</i>	2	656.00	✓ 1,312.00
REAR FLOOR PANEL <i>Repair</i>	1	739.90	+ 739.90
REAR NUMBER PLATE LAMP L/R <i>new</i>	2	111.60	+ 223.20
REAR RH DECK BOX <i>behind</i>	1	481.90	295 ✓ 481.90
REAR TAILGATE <i>Distorted</i>	1	929.60	✓ 929.60
REAR TAILGATE 'HYBRID' EMBLEM <i>} New</i>	1	50.00	✓ 50.00
REAR TAILGATE 'PRIUS' EMBLEM <i>} New</i>	1	52.30	✓ 52.30
REAR TAILGATE DAMPER L/R <i>new</i>	2	356.70	+ 713.40

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

TWINBIZ RENTAL PTE LTD
 2 KAKI BUKIT AVE 2 #01-18 KAKI BUKIT
 AUTOHUB
 SINGAPORE 417921

Contact : 91509303

TAX INVOICE

Repair Code : CLM17273

Date in : 02/07/2022

Vehicle Num. : SLS5264E

Model : TOYOTA PRIUS ALPHA 1.8S CVT

Chassis/Eng# : ZVW400026228/2ZR1990506

REAR TAILGATE INNER PULL GARNISH	<i>not new</i>	1	38.50	<i>X</i>	38.50
REAR TAILGATE INNER UPHOLSTERY TRIM GARNISH	<i>cracked</i>	1	578.00	<i>/</i>	578.00
REAR TAILGATE MECHANISM LOCK	<i>new</i>	1	425.00	<i>✓</i>	425.00
REAR TAILGATE OUTER GARNISH	<i>cracked</i>	1	427.90	<i>✓</i>	427.90
REAR TAILGATE OUTER GARNISH 'LOGO' EMBLEM	<i>new</i>	1	87.10	<i>✓</i>	87.10
REAR TAILGATE RUBBER GUIDE STOPPER L/R	<i>not new</i>	2	29.00	<i>X</i>	58.00
REAR TAILGATE WEATHER STRIP	<i>lit</i>	1	360.70	<i>✓</i>	360.70
REAR TAILGATE WINDSCREEN LOWER SEAL	<i>new</i>	2	42.00	<i>/</i>	84.00
REAR TAILGATE WINDSCREEN MOULDING L/R	<i>new</i>	2	65.00	<i>/</i>	130.00
REAR TAILGATE WINDSCREEN UPPER SEAL	<i>new</i>	1	38.00	<i>/</i>	38.00
REAR TAILLAMP BACK RUBBER SEAL L/R	<i>new</i>	2	69.50	<i>✓</i>	139.00
REAR TAILLAMP L/R	<i>cracked</i>	2	660.60	<i>✓</i>	1,321.20
REAR TAILLAMP LOWER BRACKET L/R	<i>cracked</i>	2	59.10	<i>/</i>	118.20
Subtotal before discount					12,914.70
Percentage discount 25%					3,228.68
Sub-total 1					9,686.03
REAR BUMPER CLIPS - SET	<i>new</i>	1	50.00	<i>30</i>	<i>50.00</i>
REAR BUMPER REVERSE SENSOR	<i>new</i>	1	250.00	<i>200</i>	<i>250.00</i>

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

TWINBIZ RENTAL PTE LTD
 2 KAKI BUKIT AVE 2 #01-18 KAKI BUKIT
 AUTOHUB
 SINGAPORE 417921

Contact : 91509303

TAX INVOICE

Repair Code : CLM17273
 Date in : 02/07/2022
 Vehicle Num. : SLS5264E
 Model : TOYOTA PRIUS ALPHA 1.8S CVT
 Chassis/Eng# : ZVW400026228/2ZR1990506

REAR END PANEL INNER TOP GARNISH CLIPS - SET	<i>ME</i>	1	30.00	<i>20</i>	30.00
REAR FLOOR PANEL INSULATOR MAT	<i>NEW</i>	1	300.00	<i>200</i>	300.00
REAR RH REVERSE CAMERA	<i>NEW</i>	1	500.00	<i>X</i>	500.00
REAR TAILGATE INNER UPHOLSTERY TRIM GARNISH CLIPS - SET	<i>ME</i>	1	80.00	<i>30</i>	80.00
REAR TAILGATE NUMBER PLATE	<i>Best</i>	1	25.00	<i>/</i>	25.00
REAR TAILGATE NUMBER PLATE HOLDER	<i>Del</i>	1	50.00	<i>30</i>	50.00
REAR TAILGATE OUTER GARNISH CLIPS - SET	<i>NEW</i>	1	20.00	<i>10</i>	20.00
REAR TAILGATE TOP SPOILER CLIPS - SET	<i>NEW</i>	1	50.00	<i>X</i>	50.00
REAR TAILGATE WINDSCREEN SEALANT	<i>ME</i>	1	80.00	<i>60</i>	80.00
REAR TAILLAMP CLIPS L/R - SET	<i>ME</i>	2	30.00	<i>40</i>	60.00
Subtotal before discount					1,495.00
Percentage discount 0%					0.00
Sub-total 2					1,495.00
Parts-total					11,181.03

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.	<i>✓</i>	80.00
To remove, reinstall tailgate windscreen	<i>120</i>	150.00
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	<i>60</i>	100.00
To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.	<i>800</i>	1,400.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

TWINBIZ RENTAL PTE LTD
2 KAKI BUKIT AVE 2 #01-18 KAKI BUKIT
AUTOHUB
SINGAPORE 417921

Contact : 91509303

TAX INVOICE

Repair Code : CLM17273

Date in : 02/07/2022

Vehicle Num. : SLS5264E

Model : TOYOTA PRIUS ALPHA 1.8S CVT

Chassis/Eng# : ZVW400026228/2ZR1990506

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

To transfer rear tailgate inner trim board, wiper motor, mechanism lock outer handle.

2200	1000	1,800.00
	60	120.00
		80.00
Labour Total		3,730.00
Parts & Labour Total		14,911.03

*** This is a computer-generated document which requires no signature.***

page 4

Adrian G
L/S 06/07/22

07 Days.

total: 9887.65

L/S 7.9K ✓

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: