

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Muhd Ashik B Madi

Date: 18 Jul 2022

**Preliminary Advice**

Insured Vehicle No	: EL1011P	Accident Date	: 02/07/2022
TP Vehicle No	: SJX7942R	Assignment Date	: 05/07/2022
Make	: HYUNDAI AVANTE	Est. Duration of Repair	: 10
Date of Inspection	: 06/07/2022		
Inspection At	: E M SOLUTION PTE LTD (HQ) 160 SIN MING DRIVE,, #03-18, SIN MING AUTOCITY SINGAPORE 575722		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,858.68
Revised Amount	:S\$	7,006.24
Check Items (Estimated)	:S\$	0.00
Total	:S\$	7,006.24
 Lump Sum Repair	 :S\$	 5,600.00

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is economical for repair  
 ( ) The vehicle is not economical for repair  
 ( ) Part-by-Part repair  
 ( X ) Lump Sum repair
- ( X ) The above survey was conducted on a 'without prejudice' basis. Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.