



Date of Accident : 02 July 2022

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

Mr Tan Gim Hai (Chen Jinhai)

Date : 06 July 2022

Chassis No : ACR507037554

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
01	1 pc	front bumper	\$ 546.20
02	2 ps	front bumper side retainer @ \$85.00	\$ 170.00
03	10 ps	front bumper clips @ \$5.00	\$ 50.00
04	1 pc	o/s front door	\$ 1,481.00
05	1 pc	o/s front door chrome moulding	\$ 172.00
06	1 pc	o/s front door lower protector	\$ 1,233.90
			\$ 3,653.10
		Less 25 %	\$ 913.28
			\$ 2,739.83
		<u>LABOUR & MISC. CHARGES</u>	
01		To transfer of door fittings and perform water seepage test.	\$ 150.00
02		To rust-proofing of the affected areas.	\$ 250.00
03		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 1,000.00
04		Putty and spray painting of the affected portion.	\$ 1,000.00
			\$ 2,400.00
		Total	\$ 5,139.83

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: