



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE (S'PORE) PTE
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
Registration No : SLU2354M
Chassis No : MRHFC5650HT000619
Model : CIVIC 1.6 VTI YM2017
Owner's Name : FATHUL RAHMAN BIN
Ins Policy No. :
Date of Accident : 2/7/2022

Document No. : SQT22001907 Page 1
Date : 4 Jul 2022
Customer No. : WZC008
Svc Advisor : YOU PO SOON
Engine No : R16B22001037
Date | Time : 4 Jul 2022 7:02:31 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incl GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: MR FATHUL OWNER INSURER: SOMPO ACC DATE: 2/7/2022 SURVEYED BY: DATE: REF NO: TP INSURER: C/TAIPING TP VEH: GBD822A						
60100-TEA-T00ZZ	HOOD COMPENGINE / ST.	1	683.50	25	512.62	35.88	548.50
74120-TBA-A01	LOCK ASSYHOOD X NN	1	100.40	25	75.30	5.27	80.57
80100-TBA-A02	CONDENSER ASSY / GA (photo)	1	704.40	25	528.30	36.98	565.28
71101-TEA-T00ZZ	FACEFR.BUMPER / CRA	1	579.90	25	434.92	30.44	465.36
71140-TEA-T00	BEAMR.FR.BUMPER UPPER X NN	1	30.50	25	22.87	1.60	24.47
71190-TEA-T00	BEAML.FR.BUMPER UPPER X NN	1	30.50	25	22.87	1.60	24.47
71150-TEA-T00	BEAM COMPFR.BUMPER CENTER UPP / ST.	1	245.30	25	183.97	12.88	196.85
71193-TEA-T01	SPACERR.FR.BUMPER SIDE / {acc.	1	10.40	25	7.80	0.55	8.35
71198-TEA-T01	SPACERL.FR.BUMPER SIDE / {acc.	1	10.40	25	7.80	0.55	8.35
71121-TEA-T02	BASE.FR.GRILLE CHROME / CRA	1	84.20	25	63.15	4.42	67.57
71125-TEA-T01	MOLDINGFR.GRILLE / CRA	1	114.50	25	85.87	6.01	91.88
75700-TBA-A00	EMBLEM / MLC	1	17.20	25	12.90	0.90	13.80
90301-ST0-003	NUT,PUSH 3MM / MCC	2	2.10	25	3.15	0.22	3.37
74146-TEA-T00	RUBBERHOOD SEAL X NN Nec	1	31.40	25	23.55	1.65	25.20
91555-TBA-K01	CLIPAMBIENT SENSOR / BR.	1	5.80	25	4.35	0.30	4.65
33100-TEC-Q01	HEADLIGHT ASSY.R. X NN	1	668.50	25	501.37	35.10	536.47
33150-TEC-Q01	HEADLIGHT ASSYL. X NN	1	668.50	25	501.37	35.10	536.47
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N) / GA	1	45.00		45.00	3.15	48.15
Sum Item					3037.16	212.60	3,249.76

Printed on 4/7/2022 7:11:02 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE (S'PORE) PTE
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
Registration No : SLU2354M
Chassis No : MRHFC5650HT000619
Model : CIVIC 1.6 VTI YM2017
Owner's Name : FATHUL RAHMAN BIN
Ins Policy No. :
Date of Accident : 2/7/2022

Document No. : SQT22001907
Date : 4. Jul 2022
Customer No. : WZC008
Svc Advisor : YOU PO SOON
Engine No : R16B22001037
Date | Time : 4. Jul 2022 7:02:31 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BOSUN	SUNDRIES	1	50.00	20	50.00	3.50	53.50
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	180.00	150	180.00	12.60	192.60
BMA01D	REMOVE & INSTALL A/C CONDENSER WITH FITTINGS.	1	500.00	450	500.00	35.00	535.00
BKBH01S	STRAGHTEN ALIGN BULKHEAD & RENEW DAMAGE PARTS.	1	2100.00	1300	2100.00	147.00	2247.00
BP03R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (3P)	1	1700.00	1040	1700.00	119.00	1819.00
Sum Labor					4530.00	317.10	4,847.10

Survey By : Ene Qiao
Date & Time : 2/7/22
Excess :
Status : 4 Days
Signature : before part photos.

Total Amount 7,567.16 529.70 8,096.86
Total (Inclusive of GST) 8,096.86

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts purchased on "no prejudice" basis
- Third party claims on "no prejudice" basis
- No illegal modification
- Supplier of parts must be approved and is submitted to the company

Acknowledged by:

Signature:

Date:

Printed on 4/7/2022 7:11:02 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.