



# QUOTATION

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223  
Company Ref. No.: S60FC1380G

|                         |                                        |                           |                          |             |   |
|-------------------------|----------------------------------------|---------------------------|--------------------------|-------------|---|
| <b>Customer</b>         | : CHINA TAIPING INSURANCE (S'PORE) PTE | <b>Document No.</b>       | : SQT22001907            | <b>Page</b> | 1 |
|                         | 3 ANSON ROAD #16-00                    | <b>Date</b>               | : 4. Jul 2022            |             |   |
|                         | SPRINGLEAF TOWER                       | <b>Customer No.</b>       | : WZC008                 |             |   |
|                         | SINGAPORE 079909                       | <b>Svc Advisor</b>        | : YOU PO SOON            |             |   |
| <b>Registration No</b>  | : SLU2354M                             | <b>Engine No</b>          | : R16B22001037           |             |   |
| <b>Chassis No</b>       | : MRHFC5650HT000619                    | <b>Date   Time</b>        | : 4. Jul 2022 7:02:31 PM |             |   |
| <b>Model</b>            | : CIVIC 1.6 VTI YM2017                 | <b>Surveyor Name</b>      | :                        |             |   |
| <b>Owner's Name</b>     | : FATHUL RAHMAN BIN                    | <b>Survey Date</b>        | :                        |             |   |
| <b>Ins Policy No.</b>   | :                                      | <b>Authorisation Date</b> | :                        |             |   |
| <b>Date of Accident</b> | : 2/7/2022                             |                           |                          |             |   |

| Item            | Description                         | Qty | Unit Price | Disc % | Amount  | 0% GST Amount | Amount incld GST |
|-----------------|-------------------------------------|-----|------------|--------|---------|---------------|------------------|
|                 | TP DIRECT SETTLEMENT (J/NO: )       |     |            |        |         |               |                  |
|                 | OWNER: MR FATHUL                    |     |            |        |         |               |                  |
|                 | OWNER INSURER: SOMPO                |     |            |        |         |               |                  |
|                 | ACC DATE: 2/7/2022                  |     |            |        |         |               |                  |
|                 | SURVEYED BY:                        |     |            |        |         |               |                  |
|                 | DATE:                               |     |            |        |         |               |                  |
|                 | REF NO:                             |     |            |        |         |               |                  |
|                 | TP INSURER: C/TAIPING               |     |            |        |         |               |                  |
|                 | TP VEH: GBD822A                     |     |            |        |         |               |                  |
| 60100-TEA-T00ZZ | HOOD COMPENGINE / BT.               | 1   | 683.50     | 25     | 512.62  | 35.88         | 548.50           |
| 74120-TBA-A01   | LOCK ASSYHOOD X NN                  | 1   | 100.40     | 25     | 75.30   | 5.27          | 80.57            |
| 80100-TBA-A02   | CONDENSER ASSY / GA (photo)         | 1   | 704.40     | 25     | 528.30  | 36.98         | 565.28           |
| 71101-TEA-T00ZZ | FACEFR.BUMPER / CRA                 | 1   | 579.90     | 25     | 434.92  | 30.44         | 465.36           |
| 71140-TEA-T00   | BEAMR.FR.BUMPER UPPER ?             | 1   | 30.50      | 25     | 22.87   | 1.60          | 24.47            |
| 71190-TEA-T00   | BEAML.FR.BUMPER UPPER ?             | 1   | 30.50      | 25     | 22.87   | 1.60          | 24.47            |
| 71150-TEA-T00   | BEAM COMPFR.BUMPER CENTER UPP / BT. | 1   | 245.30     | 25     | 183.97  | 12.88         | 196.85           |
| 71193-TEA-T01   | SPACERR.FR.BUMPER SIDE / GA         | 1   | 10.40      | 25     | 7.80    | 0.55          | 8.35             |
| 71198-TEA-T01   | SPACERL.FR.BUMPER SIDE / GA         | 1   | 10.40      | 25     | 7.80    | 0.55          | 8.35             |
| 71121-TEA-T02   | BASE.FR.GRILLE CHROME / CRA         | 1   | 84.20      | 25     | 63.15   | 4.42          | 67.57            |
| 71125-TEA-T01   | MOLDINGFR.GRILLE / CRA              | 1   | 114.50     | 25     | 85.87   | 6.01          | 91.88            |
| 75700-TBA-A00   | EMBLEM / MCL.                       | 1   | 17.20      | 25     | 12.90   | 0.90          | 13.80            |
| 90301-ST0-003   | NUT,PUSH 3MM / MCC                  | 2   | 2.10       | 25     | 3.15    | 0.22          | 3.37             |
| 74146-TEA-T00   | RUBBERHOOD SEAL X NN                | 1   | 31.40      | 25     | 23.55   | 1.65          | 25.20            |
| 91555-TBA-K01   | CLIPAMBIENT SENSOR / BR.            | 1   | 5.80       | 25     | 4.35    | 0.30          | 4.65             |
| 33100-TEC-Q01   | HEADLIGHT ASSY.R. X NN              | 1   | 668.50     | 25     | 501.37  | 35.10         | 536.47           |
| 33150-TEC-Q01   | HEADLIGHT ASSYL. ?                  | 1   | 668.50     | 25     | 501.37  | 35.10         | 536.47           |
| BO-NUM-COMP-L   | NUMBER PLATE WITH CASING-L(N) / GA  | 1   | 45.00      |        | 45.00   | 3.15          | 48.15            |
| Sum Item        |                                     |     |            |        | 3037.16 | 212.60        | 3,249.76         |

Printed on 4/7/2022 7:11:02 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

**QUOTATION**GST Reg No.: M200050223  
Company Ref. No.: S60FC1380G

**Customer** : CHINA TAIPING INSURANCE (S'PORE) PTE  
3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909

**Registration No** : SLU2354M

**Chassis No** : MRHFC5650HT000619

**Model** : CIVIC 1.6 VTI YM2017

**Owner's Name** : FATHUL RAHMAN BIN

**Ins Policy No.** :

**Date of Accident** : 2/7/2022

**Document No.** : SQT22001907

**Date** : 4. Jul 2022

**Customer No.** : WZC008

**Svc Advisor** : YOU PO SOON

**Engine No** : R16B22001037

**Date | Time** : 4. Jul 2022 7:02:31 PM

**Surveyor Name** :

**Survey Date** :

**Authorisation Date** :

Page 2

| Item      | Description                                        | Qty | Unit Price | Disc % | Amount  | 0% GST Amount | Amount incld GST |
|-----------|----------------------------------------------------|-----|------------|--------|---------|---------------|------------------|
| BOSUN     | SUNDRIES                                           | 1   | 50.00      | 20     | 50.00   | 3.50          | 53.50            |
| BML01I    | INSPECT FR LIGHTING MECHANISMS & FOCUS             | 1   | 180.00     | 150    | 180.00  | 12.60         | 192.60           |
| BMA01D    | REMOVE & INSTALL A/C CONDENSER WITH FITTINGS.      | 1   | 500.00     | 450    | 500.00  | 35.00         | 535.00           |
| BKBH01S   | STRAGHTEN ALIGN BULKHEAD & RENEW DAMAGE PARTS.     | 1   | 2100.00    | 1300   | 2100.00 | 147.00        | 2247.00          |
| BP03R     | SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (3P) | 1   | 1700.00    | 1040   | 1700.00 | 119.00        | 1819.00          |
| Sum Labor |                                                    |     |            |        | 4530.00 | 317.10        | 4,847.10         |

Survey By

Date &amp; Time

Excess

Status

Signature

Total Amount 7,567.16 529.70 8,096.86

Total (Inclusive of GST) 8,096.86

before paint photos.

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are based on information
- Third party claims on "No Prejudice" basis
- No illegal modification is allowed
- Supplier must be approved and is subject to the Company

Acknowledged by:

Signature:

Date:

Printed on 4/7/2022 7:11:02 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.