

# Munich Autocare Pte Ltd

60 Jalan Lam Huat #02-02/03 Carros Centre Singapore 737869

Tel: +65 6255 2288 | Fax: +65 6265 5388

Company Reg. No.: 201832250M | GST Reg. No.: 201832250M

## Tax Invoice

**ALLIANZ INSURANCE SINGAPORE PTE LTD**

Inv No. : BPINV22110047  
Invoice Date : 14 Nov 2022  
Ref : BPWJ2211046  
Terms : COD  
Veh. No. : SMA138C

| #  | Description                        | Qty  | UOM | U/P      | Amt      |
|----|------------------------------------|------|-----|----------|----------|
| 1  | RAD AIR DUCT BMW X3 FRT TOP        | 1.00 |     | 216.10   | 216.10   |
| 2  | BOOT EMBLEM BMW X3 G01-S-DRIVE 201 | 1.00 |     | 159.50   | 159.50   |
| 3  | BUMPER SPOILER BMW X3 GO1 REAR     | 1.00 |     | 790.00   | 790.00   |
| 4  | BATTERY CABLE BMW G01              | 1.00 |     | 319.00   | 319.00   |
| 5  | BOOT BMW X3 G01                    | 1.00 |     | 1,700.00 | 1,700.00 |
| 6  | BOOT EMBLEM BMW X3 G01             | 1.00 |     | 94.25    | 94.25    |
| 7  | BOOT EMBLEM BMW X3                 | 1.00 |     | 108.75   | 108.75   |
| 8  | T/LAMP BMW X3 GO1 R/LH             | 1.00 |     | 401.35   | 401.35   |
| 9  | T/LAMP BMW X3 G01 R/RH             | 1.00 |     | 401.35   | 401.35   |
| 10 | T/LAMP BMW X3 G01 R/LH             | 1.00 |     | 508.40   | 508.40   |
| 11 | T/LAMP BMW X3 G01 R/RH             | 1.00 |     | 508.40   | 508.40   |
| 12 | BUMPER BMW X3 G01 REAR             | 1.00 |     | 1,539.85 | 1,539.85 |
| 13 | EX PIPE CHROME BMW X3 G01 R/LH=RH  | 1.00 |     | 152.25   | 152.25   |
| 14 | BONNET EMBLEM BMW X3 G01 BMW       | 1.00 |     | 101.50   | 101.50   |
| 15 | BONNET EMBLEM BMW X3 G01           | 1.00 |     | 1,901.40 | 1,901.40 |
| 16 | RAD GRILLE BMW X3 G01 LH           | 1.00 |     | 166.75   | 166.75   |
| 17 | RAD GRILLE BMW X3 G01 RH           | 1.00 |     | 166.75   | 166.75   |
| 18 | BOOT INNER TRIM BMW X3 G01         | 1.00 |     | 961.40   | 961.40   |
| 19 | FRONT BUMPER                       | 1.00 |     | 1,406.25 | 1,406.25 |

Continue on next page...

# Munich Autocare Pte Ltd

60 Jalan Lam Huat #02-02/03 Carros Centre Singapore 737869

Tel: +65 6255 2288 | Fax: +65 6265 5388

Company Reg. No.: 201832250M | GST Reg. No.: 201832250M

## Tax Invoice

**ALLIANZ INSURANCE SINGAPORE PTE LTD**

Inv No. : BPINV22110047  
Invoice Date : 14 Nov 2022  
Ref : BPWJ2211046  
Terms : COD  
Veh. No. : SMA138C

| #  | Description                         | Qty  | UOM | U/P      | Amt      |
|----|-------------------------------------|------|-----|----------|----------|
| 20 | ROOF AIR BAG BMW X3 G01 LH          | 1.00 |     | 1,270.00 | 1,270.00 |
| 21 | 72127396862                         | 1.00 |     | 1,270.00 | 1,270.00 |
| 22 | SEAT BELT BMW X3 G01 F/RH           | 1.00 |     | 1,120.80 | 1,120.80 |
| 23 | ROOF LINING BMW X3 G01              | 1.00 |     | 2,018.00 | 2,018.00 |
| 24 | BOOT RUBBER BMW X3 G01              | 1.00 |     | 268.25   | 268.25   |
| 25 | SEAT BELT BRACKET BMW X3 G01F/RH    | 1.00 |     | 416.00   | 416.00   |
| 26 | EX PIPE BKT BMW X3 R/LH             | 1.00 |     | 277.50   | 277.50   |
| 27 | EX PIPE BKT BMW X3 R/RH             | 1.00 |     | 57.00    | 57.00    |
| 28 | BUMPER REINF BKT BMW X3 F/LH=RH     | 1.00 |     | 98.60    | 98.60    |
| 29 | BUMPER REINF BMW X3 FRT TOP         | 1.00 |     | 711.25   | 711.25   |
| 30 | BUMPER REINF BMW X3 REAR            | 1.00 |     | 850.00   | 850.00   |
| 31 | PARKING SENSOR HARNESS BMW X3 REAR  | 1.00 |     | 401.60   | 401.60   |
| 32 | BUMPER SPOILER BMW X3 FRT           | 1.00 |     | 790.00   | 790.00   |
| 33 | BOOT LOCK BMW X3                    | 1.00 |     | 302.50   | 302.50   |
| 34 | BRAKE AIR DUCT BMW X3 F/LH          | 1.00 |     | 93.00    | 93.00    |
| 35 | RAD AIR DUCT BMW X3 FRT CTR TOP     | 1.00 |     | 275.50   | 275.50   |
| 36 | BUMPER REINF BMW X3 REAR BOTTOM     | 1.00 |     | 120.00   | 120.00   |
| 37 | BUMPER GRILLE INNER BASE BMW X3 FRT | 1.00 |     | 127.60   | 127.60   |
| 38 | BUMPER UNDER COVER BMW X3 FRT       | 1.00 |     | 240.00   | 240.00   |

Continue on next page...

# Munich Autocare Pte Ltd

60 Jalan Lam Huat #02-02/03 Carros Centre Singapore 737869

Tel: +65 6255 2288 | Fax: +65 6265 5388

Company Reg. No.: 201832250M | GST Reg. No.: 201832250M

## Tax Invoice

**ALLIANZ INSURANCE SINGAPORE PTE LTD**

**Inv No.** : BPINV22110047  
**Invoice Date** : 14 Nov 2022  
**Ref** : BPWJ2211046  
**Terms** : COD  
**Veh. No.** : SMA138C

| #  | Description                                      | Qty   | UOM | U/P       | Amt       |
|----|--------------------------------------------------|-------|-----|-----------|-----------|
| 39 | RAD AIR DUCT BMW X3 FRT CTR BOT                  | 1.00  |     | 203.00    | 203.00    |
| 40 | BUMPER UNDER COVER BMW X3 REAR CHROME            | 1.00  |     | 360.00    | 360.00    |
| 41 | BUMPER BKT BMW X3 R/LH CTR                       | 1.00  |     | 181.25    | 181.25    |
| 42 | BUMPER BKT BMW X3 R/RH CTR                       | 1.00  |     | 181.25    | 181.25    |
| 43 | BUMPER TOW COVER BMW X3 REAR                     | 1.00  |     | 65.25     | 65.25     |
| 44 | REVERSE SENSOR VW BMW X3 FRT/RR                  | 2.00  |     | 156.00    | 312.00    |
| 45 | REVERSE SENSOR VW BMW X3 FRT/RR                  | 1.00  |     | 137.75    | 137.75    |
| 46 | BUMPER REFLECTOR BMW X3 R/LH                     | 1.00  |     | 108.00    | 108.00    |
| 47 | BUMPER REFLECTOR BMW X3 R/RH                     | 1.00  |     | 0.00      | 0.00      |
| 48 | TAIL LAMP TRIM RH                                | 1.00  |     | 137.50    | 137.50    |
| 49 | FRONT RADIATOR AIR DUCT                          | 1.00  |     | 142.10    | 142.10    |
| 50 | FRONT BUMPER ABSORBER                            | 1.00  |     | 104.00    | 104.00    |
| 51 | B+ JUNCTION                                      | 1.00  |     | 241.55    | 241.55    |
| 52 | AIRBAG COMPUTER UNIT                             | 1.00  |     | 1,770.00  | 1,770.00  |
| 53 | LESS 5%                                          | 1.00  |     | -1,312.72 | -1,312.72 |
| 54 | RIVET BOOT BMW X3 REAR                           | 4.00  |     | 10.50     | 42.00     |
| 55 | REAR BUMPER CLIPS SET                            | 12.00 |     | 7.00      | 84.00     |
| 56 | REAR TAILGATE WINDSCREEN SEALANT WITH PRIMER SET | 1.00  |     | 40.00     | 40.00     |
| 57 | FRONT BUMPER CLIP SET                            | 12.00 |     | 7.00      | 84.00     |

Continue on next page...

# Munich Autocare Pte Ltd

60 Jalan Lam Huat #02-02/03 Carros Centre Singapore 737869

Tel: +65 6255 2288 | Fax: +65 6265 5388

Company Reg. No.: 201832250M | GST Reg. No.: 201832250M

## Tax Invoice

**ALLIANZ INSURANCE SINGAPORE PTE LTD**

**Inv No.** : BPINV22110047  
**Invoice Date** : 14 Nov 2022  
**Ref** : BPWJ2211046  
**Terms** : COD  
**Veh. No.** : SMA138C

| #  | Description                                                                                                                                                           | Qty  | UOM | U/P    | Amt    |
|----|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----|--------|--------|
| 58 | BP-Labour for welding realign accident front portion bumper, bonnet, fender LH/RH, winds sub frame and all necessary etc                                              | 1.00 |     | 600.00 | 600.00 |
| 59 | BP-Labour for dismantle & reifx front seat RH and tensioner RH & buckle RH                                                                                            | 1.00 |     | 120.00 | 120.00 |
| 60 | BP-Labour for dismantle roof lining and install all electrical compartment, control units and side compartment trim board to replace right side cushion air bag LH/RH | 1.00 |     | 150.00 | 150.00 |
| 61 | BP-Labour for conduct re-programme and resetting of air bag seats belts reset and ECU system to clear fault code                                                      | 1.00 |     | 200.00 | 200.00 |
| 62 | BP-Labour for remove and refix rear windscreen glass                                                                                                                  | 1.00 |     | 120.00 | 120.00 |
| 63 | BP-Labour for rust-proofing of the affected areas                                                                                                                     | 1.00 |     | 60.00  | 60.00  |
| 64 | BP-Labour for remove and refix battery terminal cable (plus pole)                                                                                                     | 1.00 |     | 50.00  | 50.00  |
| 65 | Towing Charge                                                                                                                                                         | 1.00 |     | 60.00  | 60.00  |
| 66 | BP-Labour for respray accident front portion, bonnet, bumper, fender LH/RH, chassis member LH/RH and necessary etc                                                    | 1.00 |     | 800.00 | 800.00 |
| 67 | BP-Labour for welding realign accident rear portion bumper, tailgate, fender RH/LH, winds sub frame and all necessary etc                                             | 1.00 |     | 700.00 | 700.00 |
| 68 | BP-Labour for respray accident rear portions, tailgate, bumper, fender LH/RH, chassis member LH/RH and necessary etc                                                  | 1.00 |     | 800.00 | 800.00 |
| 69 | BP-Labour for check electrical wiring system of rear section for proper function including adjustment of rear tailgate & taillamp LH/RH and front headlamp LH/RH      | 1.00 |     | 40.00  | 40.00  |
| 70 | BP-Labour for dismantle & renew reverse sensor and parking sensor                                                                                                     | 1.00 |     | 60.00  | 60.00  |

Continue on next page...

# Munich Autocare Pte Ltd

60 Jalan Lam Huat #02-02/03 Carros Centre Singapore 737869

Tel: +65 6255 2288 | Fax: +65 6265 5388

Company Reg. No.: 201832250M | GST Reg. No.: 201832250M

## Tax Invoice

**ALLIANZ INSURANCE SINGAPORE PTE LTD**

Inv No. : BPINV22110047  
Invoice Date : 14 Nov 2022  
Ref : BPWJ2211046  
Terms : COD  
Veh. No. : SMA138C

| #  | Description                                                                                       | Qty  | UOM | U/P   | Amt   |
|----|---------------------------------------------------------------------------------------------------|------|-----|-------|-------|
| 71 | BP-Labour for remove & install luggage compartment and side fender inner trim to acilitate repair | 1.00 |     | 60.00 | 60.00 |
| 72 | BP-Labour for test rear portion water seepage                                                     | 1.00 |     | 20.00 | 20.00 |

### Remarks:

LKK REF: CC4/AIS22006420/KGA3

DOA: 3.7.2022

ALL PAYMENT SHOULD BE MADE PAYABLE TO MUNICH AUTOCARE PTE LTD  
BANK : UOB BANK  
BANK CODE : 7375  
BRANCH CODE : 001  
ACCOUNT NO. : 4513099651

Subtotal : S\$ 29,031.78  
GST 7.0% : S\$ 2,032.22  
**Total : S\$ 31,064.00**

*I agree to the price as listed above and affirm that the goods are received in good condition.*

For **Munich Autocare Pte Ltd**



(Customer's Signature and Company Stamp)

(Authorised Signature)