



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22006424/Aqy3m4	
			Date: 20/03/2023	
			Code: SMO	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SMZ 6606Y	Veh. Inspected	SNE 8606H
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2202317/GPL	Excess (\$)	0.00
	Assign From	HENRY IRENE JAMES	Assign Date	05/07/2022
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	MERCEDES BENZ GLA180	c.c	1595
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	WDC1569422J163068	Colour	GREY
	Odometer	106381 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	235/50 R18	PIRELLI	6 mm
	L/H Front Tyre	235/50 R18	PIRELLI	6 mm
	R/H Rear Tyre	235/50 R18	PIRELLI	6 mm
	L/H Rear Tyre	235/50 R18	PIRELLI	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND FRONT O/S PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	04/07/2022	Inspection Date	05/07/2022
	Survey held at	AUTOMOBILE HUB ENTERPRISE 1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY SINGAPORE 417883		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		11 Working Days	