

AUTOMOBILE HUB ENTERPRISE

1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY@KAKI BUKIT
SINGAPORE 417883

TP Sampo
Xiao Chen.

Page No. 1

Vehicle No. SNE8606H

MERCEDES BENZ GLA180

WDC1569422J163068

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR ADJUSTMENT
	<u>PARTS (LIST ITEMS)</u>			
1	REAR BUMPER <i>Delud</i>		1366.00	✓
2	REAR BUMPER SIDE HOLDER <i>NEW</i>		75.00	✓
3	REAR BUMPER LOWER GARNISH <i>Delud</i>		602.00	✓
4	REAR BUMPER SENSOR @268 <i>1 piece damaged</i>		536.00	<i>268.</i>
5	TAILLAMP <i>Crushed</i>		676.00	✓
6	TAILLAMP PANEL <i>Distorted</i>		342.00	✓
7	REAR FENDER <i>Distorted</i>		1758.00	✓
8	REAR FENDER ARC GARNISH <i>Delud</i>		249.00	✓
9	REAR FENDER AIR VENT <i>Crushed</i>		59.00	✓
10	REAR DOOR <i>Repair</i>		2082.00	+
11	REAR DOOR LOCK <i>Green</i>		379.00	+
12	REAR DOOR WEATHERSTRIPE		382.00	+
13	FUEL COVER <i>Bent</i>		72.00	✓
14	FUEL COVER LOCK <i>NEW</i>		68.00	+
15	FUEL COVER INNER GARNISH <i>Delud</i>		145.00	✓
16	REAR WHEEL RIM <i>Cr</i>		1205.00	<i>800(SN).</i>
17	REAR LOWER ARM <i>Bent</i>		862.00	✓
18	REAR CONTROL ARM <i>Bent</i>		325.00	✓
19	REAR SHOCK ABSORBER <i>Bent</i>		521.00	✓
20	REAR KNUCKLE ARM <i>Damaged</i>		988.00	✓
21	REAR WHEEL HUB C/W BEARING <i>Damaged</i>		425.00	✓
22	REAR TRAILING ARM <i>Bent</i>		389.00	✓
23	REAR STAY ARM <i>Bent</i>		314.00	✓
24	REAR ANTI ROLL BAR <i>NEW</i>		412.00	+
25	REAR ANTI ROLL BAR LINKAGE <i>NEW</i>		68.00	+
26	REAR SUB FRAME <i>Bent</i>	<i>14939</i>	1920.00	✓
27	REAR HANDBRAKE MOTOR <i>Damaged</i>	<i>13445/10</i>	887.00	✓
28	FRONT WHEEL RIM <i>Cr</i>	<i>SN 1600</i>	1205.00	<i>800(SN).</i>
29	FRONT LOWER ARM <i>Bent</i>		612.00	✓
30	FRONT KNUCKLE ARM <i>Bent</i>		1027.00	✓
31	FRONT SHOCK ABSORBER		693.00	✓
32	FRONT WHEEL HUB C/W BEARING <i>damaged</i>		464.00	✓
	<i>Rear LH Fender Inner Shield. 234</i>	✓	19742.00	
	<i>com</i>	less 10%	1974.20	10%
			17767.80	
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BUMPER CLIPS <i>NEW</i>		50.00	✓
2	REAR FENDER ARC GARNISH CLIPS <i>new</i>		20.00	✓
3	REAR TYRE <i>Punctured</i>		350.00	<i>200</i>
4	FRONT TYRE <i>NEW</i>		350.00	+
5	FRONT LH TYRE <i>New Buyer Top Chrome new</i>		250.00	<i>200</i>
	Total Parts		1020.00	

AUTOMOBILE HUB ENTERPRISE

1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY@KAKI BUKIT
SINGAPORE 417883

Page No. 2

Vehicle No. 3NE8606H

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT (S\$)
	<u>LABOUR</u>		
1	PANEL BEATING	1600.00	1000
2	SPRAY PAINTING	1000.00	800
3	WIRING	100.00	30
4	TO APPLY TUFF COAT	150.00	80
5	TO REMOVE UPHOLSTERY	150.00	80
6	TO TRANSFER REAR DOOR FITTINGS	150.00	
7	TO REMOVE FUEL TANK	150.00	60
8	TO REMOVE REAR UNDERCARRIAGE	550.00	400
9	TO REMOVE FRONT UNDERCARRIAGE	350.00	220
10	TO PERFORM WHEEL ALIGNMENT	150.00	80
11	TOWING FEES	150.00	
	Labour Total :	4500.00	
	TOTAL (PARTS & LABOUR):	23287.80	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 18415.10

2/s: 14-7K.

11 Days