

E M Solution Pte Ltd

160 Sin Ming Drive #03-18/19, Sin Ming Autocity
Singapore 575722
Tel: 64560226 Fax: 64584500
GST Reg. No: 201016308K

*Not Asstained
11 Pny @ 320dk
Recovery After Paint
4 days*

ESTIMATE

Mr **Chua Kwee Soon**
Blk 200 Pasir Panjang Rd #01-09
Singapore 118571

Date :
Veh No : **SMZ 3677L**
Make/Model : **Nissan Sylphy**
Chassis No : MNTBBAB17Z0035269
Date of Acc : 04.07.22
TP Veh No : GBK 8231R

S/No	Qty	Description	Unit Price	Amount
Materials (Nett)				
1	1 pc	Rear Boot Lid <i>762.60</i>		\$ <i>BT</i> 762.60 <i>X</i>
2	1 pc	Rear Boot Lid inner Trim		\$ <i>Pr</i> 164.20 <i>X</i>
3	1 pc	Rear Boot Lid Sylphy Emblem <i>97.60</i>		\$ <i>Ma</i> 113.30 <i>✓</i>
4	1 pc	Rear Boot Lid Nissan Logo		\$ <i>Ma</i> 60.90 <i>✓</i>
5	1 pc	Rear Boot Lid Outer Chrome Moulding		\$ <i>Ma</i> 219.40 <i>✓</i>
6	1 pc	Rear Boot Lid Mechanism Lock		\$ <i>Ma</i> 93.30 <i>✓</i>
7	1 pc	Rear Boot Weatherstrip		\$ <i>Ma</i> 105.10 <i>✓</i>
8	2 pcs	Tail Lamp L/R <i>ols m/c ma</i>	409.10	\$ 818.20 <i>✓</i>
9	1 pc	Rear Bumper <i>669.</i>		\$ <i>Ma</i> 749.90 <i>✓</i>
10	2 pcs	Rear Bumper Side Retainer L/R	\$ 43.80	\$ <i>ols ma</i> 87.60 <i>✓</i>
11	1 pc	Rear Bumper Inner Sponge		\$ <i>Ma</i> 155.90 <i>✓</i>
12	1 pc	Rear End Panel		\$ <i>Pr</i> 520.60 <i>X</i>
13	1 pc	Rear End Panel Top Garnish		\$ <i>Ma</i> 117.10 <i>✓</i>
				\$ 3,968.10
Less 10%				\$ 396.81
Parts Total :				\$ 3,571.29
Special Nett				
1	1 set	Rear Bumper Clips		\$ <i>Ma</i> 45.00 <i>-</i>
2	1 set	Rear End Top Garnish Clips		\$ <i>Ma</i> 35.00 <i>-</i>
3	1 set	Rear Boot Lid Trim Board Clips		\$ <i>Ma</i> 35.00 <i>X</i>
4	1 set	Reverse Sensor		\$ <i>Ma</i> 250.00 <i>200in</i>
Special Nett :				\$ 365.00
Labour				
1		To remove & rearrange electrical wirings, check lightings		\$ 80.00 <i>201</i>
2		To remove & replace upholstery, trim garnishes to facilitate repairs		\$ 100.00 <i>501</i>
3		To remove, transfer boot lid components		\$ 80.00 <i>501</i>
4		To remove, repair & replace damaged bodyparts and where consistent to the accident.		\$ 800.00 <i>5001</i>
5		Putty and respray painting on affected portions.		\$ 700.00 <i>6001</i>
6		To remove & renew reverse sensor		\$ 80.00 <i>501</i>
7		Rust proofing on affected portions.		\$ 80.00 <i>301</i>
Labour Total :				\$ 1,920.00
Total Parts & Labour :				\$ 5,856.29

Signature

for E M Solution Pte Ltd

LK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts for confirmation
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____