

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22006430/AQY3Q2**Date:** 26/09/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00084032200	
Claimant Vehicle No :	SJA7755K	Insured Vehicle No :	SLC5584R	
Date of Loss:	01/07/2022	Nature of Claim:	TP	Claim No: SNM22D204615/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJA7755K		Engine No:	CVK075309
Make & Model:	AUDI A4, 2.0 (A)		Chassis No:	WAUZZZF46KN006240
Reg. Date:	30/01/2019 (Man. Year: 2018)		Odometer:	27896 km
Colour:	Black			
Engine Capacity:	1984 cc			
Market Value/New Car Price:	N/A			
Sum Insured (\$\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,303.00	5,583.60	2,719.40	32.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,952.00	1,952.00	2,000.00	50.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	12,255.00	7,535.60	4,719.40	38.51
+ GST 7.00/7.00% (\$\$)	857.85	527.49	330.36	38.51
Nett Amount (\$\$)	13,112.85	8,063.09	5,049.76	38.51

INSPECTION

Date of Assignment:	05/07/2022		
Date Inspected:	07/07/2022	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Sep 2022)
Parts:	143	AUDI A4 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJA7755K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	3,188.00 FS	*3,188.00 FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	480.00 FS	*- FS
3	1		*REAR BUMPER SECURING STRIPS	Necessary	249.00 FS	*248.50 FS
4	1		*REAR BUMPER SPOILER	Cut	276.00 FS	*276.00 FS
5	1		*REAR BUMPER TRIM	Cracked	326.00 FS	*326.00 FS
6	2		*REAR BUMPER BRACKET -LH/RH	Not Necessary	260.00 FS	*- FS
7	2		*REAR LIGHT REFLECTOR REAR -LH/RH	Not Necessary	92.00 FS	*- FS
8	1		*REAR BUMPER REINFORCEMENT BEAM	Bent	1,131.00 FS	*1,131.00 FS
9	2		*REAR BUMPER SEAL	Necessary	32.00 FS	*31.60 FS
10	2		*REAR BUMPER GUIDE SECTION -LH/RH	Not Necessary	52.00 FS	*- FS
11	2		*REAR BUMPER GUIDE SECTION PIN	Not Necessary	6.00 FS	*- FS
12	2		*REAR BUMPER HOLDING STRAP	Not Necessary	188.00 FS	*- FS
13	2		*REAR BUMPER SENSOR INNER /OUTER -RH	Not Necessary	265.00 FS	*- FS
14	4		*REAR PARKING AID SEAL RING	Not Necessary	10.00 FS	*- FS
15	1		*REAR LID CONTROL UNIT	Not Necessary	454.00 FS	*- FS
16	1		*REAR LID KICK SENSOR LINE	Not Necessary	228.00 FS	*- FS
17	1		*REAR EXHAUST TAIL PIPE CHROME TRIM -LH/RH	N/S Cut	766.00 FS	*382.50 FS
18	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	8,303.00	5,583.60
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR	New	360.00	360.00
2	TO DISMANTLE AND RENEW REAR BUMPER .TO REPAIR REAR END PANELLING RE-ORGANISE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	1,400.00	700.00
3	TO RESPRAY REAR BUMPER AND REAR END PANELLING	New	2,000.00	700.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			3,952.00	1,952.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >