

Car-in 10/8/22 wip: 31447

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

Bona.

Xiao Chen.

China Taiping
— Adrian

3 days

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SIA 7755 K

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER <i>Rehand</i>	1	\$ 3,188.00	✓
2	REAR BUMPER FIXING PARTS <i>new</i>	1	\$ 480.00	+
3	REAR BUMPER SECURING STRIPS <i>new</i>	1	\$ 249.00	✓ <i>HLs</i>
4	REAR BUMPER SPOILER <i>at</i>	1	\$ 276.00	✓
5	REAR BUMPER TRIM <i>crushed</i>	1	\$ 326.00	✓
6	REAR BUMPER BRACKET - LH / RH <i>new</i>	2	\$ 260.00	+
7	REAR LIGHT REFLECTOR REAR - LH / RH <i>new</i>	2	\$ 92.00	+
8	REAR BUMPER REINFORCEMENT BEAM <i>best</i>	1	\$ 1,131.00	✓ <i>HLs</i>
9	REAR BUMPER SEAL <i>new</i>	2	\$ 32.00	✓ <i>HLs</i>
10	REAR BUMPER GUIDE SECTION - LH / RH <i>new</i>	2	\$ 52.00	+
11	REAR BUMPER GUIDE SECTION PIN <i>HL</i>	2	\$ 6.00	+
12	REAR BUMPER HOLDING STRAP <i>HL</i>	2	\$ 188.00	+
13	REAR BUMPER SENSOR INNER/ OUTER - RH <i>new</i>	2	\$ 265.00	+
14	REAR PARKING AID SEAL RING <i>HL</i>	4	\$ 10.00	+
15	REAR LID CONTROL UNIT <i>HL</i>	1	\$ 454.00	+
16	REAR LID KICK SENSOR LINE <i>HL</i>	1	\$ 228.00	+
17	REAR EXHAUST TAIL PIPE CHROME TRIM - LH / RH <i>HL</i>	2	\$ 766.00	+
18	SUNDRIES	1	\$ 300.00	?

TOTAL SPARE PARTS

: \$ 19,382.00

TOTAL LABOUR CHARGES

: \$ 3,952.00

GRAND TOTAL

: \$ 23,334.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

Adrian Lj
Resigned
HLs