

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/559/2022/EQ
DATE : 05-Jul-22
WIP : 31447

Xiao Chen,
03 days slip
\$7535.60.

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY 07/07/2022

YOUR INSURED VEH NO : SLC 5584 R

China Taiping Insurance (S) Pte Ltd

3 Anson Road

#16-00 Springleaf Tower

Singapore 079909

OWNER'S NAME : MR ZAINUDIN BIN ABU BAKAR
ADDRESS : 25 WEST COAST CRESCENT
#21-17
SINGAPORE 128047
TELEPHONE : HP +65 9088 2155
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : MPC22P00019000
VEHICLE NO : **SJA 7755 K**
MODEL CODE : AUDI A4 SEDAN 2.0 TFSI 8W
MODEL YEAR : 30-01-2019
ENGINE NO : CVK 075309
CHASSIS NO : WAUZZZF46KN006240
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 01-Jul-22
PLACE OF ACCIDENT : ALONG PASIR PANJANG ROAD

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJA 7755 K

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$ 360.00	✓✓
2	TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR REAR END PANELLING. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,400.00	700 ✓
3	TO RESPRAY REAR BUMPER AND REAR END PANELLING	\$ 2,000.00	700 ✓
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 3,952.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJA 7755 K

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER <i>Debond</i>	1	S 3,188.00	✓
2	REAR BUMPER FIXING PARTS <i>new</i>	1	S 480.00	+
3	REAR BUMPER SECURING STRIPS new <i>nec</i>	1	S 249.00	✓ 248.50 ✓
4	REAR BUMPER SPOILER <i>cut</i>	1	S 276.00	✓
5	REAR BUMPER TRIM <i>crushed</i>	1	S 326.00	✓
6	REAR BUMPER BRACKET - LH / RH <i>new</i>	2	S 260.00	+
7	REAR LIGHT REFLECTOR REAR - LH / RH	2	S 92.00	+
8	REAR BUMPER REINFORCEMENT BEAM <i>? Bent</i>	1	S 1,131.00	✓
9	REAR BUMPER SEAL <i>? Nec</i>	2	S 32.00	✓ 31.60 ✓
10	REAR BUMPER GUIDE SECTION - LH / RH <i>new</i>	2	S 52.00	+
11	REAR BUMPER GUIDE SECTION PIN <i>new</i>	2	S 6.00	+
12	REAR BUMPER HOLDING STRAP <i>new</i>	2	S 188.00	+
13	REAR BUMPER SENSOR INNER/ OUTER - RH <i>new</i>	2	S 265.00	+
14	REAR PARKING AID SEAL RING <i>new</i>	4	S 10.00	+
15	REAR LID CONTROL UNIT <i>new</i>	1	S 454.00	+
16	REAR LID KICK SENSOR LINE	1	S 228.00	+
17	REAR EXHAUST TAIL PIPE CHROME TRIM - LH / RH <i>LH cut</i>	2	S 766.00	✓ 382.50 ✓
18	SUNDRIES <i>Not nec</i>	1	S 300.00	✗
TOTAL SPARE PARTS		:	\$ 19,382.00	8303
TOTAL LABOUR CHARGES		:	\$ 3,952.00	
GRAND TOTAL		:	\$ 23,334.00	12255

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Lim*
SURVEYED DATE : *07/07/22*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 03 days. H.S.*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT