

TP 1st Cap- SMJ 5175P - 2019 March.
Xiao Chen. Honda Fit 1317 CC
GK31344985

Rear Number Plate	2 NP	30(SN) +
Rear Number Plate Holder	new	30(SN) +
Rear Bumper	Dehd	539.70 ✓
Rear Bumper Clips.	new	30(SN) ✓
Rear Bumper Side Holder	new	$25.8 \times 2 = 51.60$ ✓
Rear Bumper Centre Moulding	new	124.10 ✓
Rear Bumper Side Moulding	x 02	$69.2 \times 2 = 138.40$ ✓
Reverse Sensor	Damaged	280(SN) 200(SN)
Rear End Panel	Dented	562.20 ✓
Rear End Panel Top Garnish.	Dehd	121.80 ✓
Rear End Panel Top Garnish Clips.	new	20(SN) ✓
Rear End Panel Sealant.	new	60(SN) ✓
Rear End Panel Buzzer	Damaged	95.20 ✓
Rear End Panel Antenna Sensor	Damaged	127.40 ✓

SMJ5175P.

Taillap x 02	cut	376.2 x 2 = 752.40 ✓
Tailgate	Dented	955.20 ✓
Tailgate Lock	Damaged	269.60 ✓
Tailgate Weatherstripe	cut	208.50 ✓
Tailgate Inner Trim Board	cracked	345.90 ✓
Tailgate Inner Trim Board clips	new	30(SN) ✓
Tailgate Outer Garnish		263.20 ✗
Tailgate Outer Garnish Clips	new	20(SN) ✗
Tailgate G(4) Moulding		122.90 ✓
Tailgate G(5) Sealant	new	60(SN) ✓
Honda Logo	not new	38.90 ✗
Fit Emblem	new	45.80 ✓
Rees Camera	new	480(SN) ✗
Spare Tyre Panel Top Board	cracked	252.20 ✓
Tools Tray Sponge	cracked	289.40 ✓
Rees Fender Inner Trim Cover x 02	new	288.5 x 2 = 577 ✓
Rees Fender Inner Trim Cover Clips	new	60(SN) 30(SN)

SMT 5175P.

Panel Beating.

Spray Painting.

Wiring.

To spray tuff coat

To remove reverse sensor

To remove rear camera.

To remove video recorder.

To remove upholstery.

To transfer tailgate fittings.

To remove tailgate glass

~~1200~~ 800

~~1200~~ 800

~~50~~ 30

~~150~~ 80

~~100~~ 50

~~100~~ 50

~~100~~ 50

~~150~~ 80

~~150~~ 80

~~180~~ 120.

List: 5579.30

Ten 20%: 4463.44

S.N: 400

Labour: 2140

Total: 7003.44

H/S: 56K

06 Days

5600

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: