

SY6108C 2019 Sept.

TP Ergo
Veron.

Lexus RX300 1998 cc

JTJBAMCA 702072350

Rees Bumper

Distorted.

995 ✓

Rees Bumper Clips.

Hee

50(SN) ✓

Rees Bumper Side Holder x 02

Not New

81.9 x 2 = 163.80 ✓

Rees Bumper lower Garnish.

Distorted

361.40 ✓

Rees Bumper Reflector x 02

Not New

185.6 x 2 = 371.20 ✓

Rees Bumper Sponge

Crushed

266.90 ✓

Rees Bumper Reinforcement Best

568.80 ✓

Rees Bumper Exhaust Chrome x 02

Not New

325.1 x 2 = 650.20 ✓

Rees Bumper lower Bracket x 02

Best

35.1 x 2 = 70.20 ✓

Reverse Sensor x 04.

2 pieces damaged

708.20
354.1 x 4 = 1416.40 ✓

Reverse Sensor Holder x 04.

Not New

25 x 4 = 100 ✓

Rees End Panel.

Reps

926.30 ✓

Rees End Panel Top Garnish.

Not New

321.50 ✓

6261.70

SY 6108C

Rees End Panel Top Garnish Clips.	20(SN) X
Rees End Panel Sealant.	60(SN) X
Tailgate Dented.	3263 2689
Tailgate Lock	1006.40 X
Tailgate Weatherstripe.	458.80 X
Tailgate Glass Moulding.	185. 245.90 ✓
Tailgate Glass Sealant.	60(SN) ✓
Lexus Logo.	85.90 ✓
Lexus Wordimg.	42.50 ✓
RX 300 Wordimg.	1245. 1485.40 ✓
Rees Exhaust Pipe.	Best 45.90 X
Rees Exhaust Pipe Mounting.	35.50 ✓
Rees Exhaust Pipe Gasket	369.80 245.40
Rees Exhaust Heat Shield.	Dented

SY6108C

1689

Centre Exhaust Pipe

But

~~1854.90~~ ✓

9988

S.N: 110

8989.20

Panel Beating

~~1000~~

500

Spray Painting

~~1000~~

500

Wiring

~~100~~

30

To remove cruise sensor

~~100~~

50

To remove rear camera

~~100~~

50

To remove rear video recorder

100 X

To remove upholstery

~~150~~

40

1850

To spray tuff coat

~~150~~

40

To transfer tailgate fittings

~~150~~

X 80

To remove tailgate g/l's

~~180~~

X 120

To remove rear and centre exhaust pipes. ~~300~~ 160.

5384.90

18,875.70

Total: 10649.20

L/S: 8.5K

05 Days

8.5K

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: