

TPFRgo.  
Carline.

SMM2883H. 2019 June  
Honda Vezel 1496cc  
RU11319019.

Rear Number Plate	} <sup>NIPT</sup> <sub>new</sub>	30(SW) +
Rear Number Plate Holder		30(SW) +
Rear Bumper Deband		745.40 /
Rear Bumper Clips. <sup>new</sup>		30(SW) /
Rear Bumper Side Holder x 02 <sup>new</sup>		32.4 x 2 = 64.80 /
Rear Bumper Reflector x 02 <sup>NIPT</sup> <sub>new</sub>		141.1 x 2 = 282.20 +
Rear Bumper Side Garnish x 02 <sup>NIPT</sup> <sub>new</sub>		195 x 2 = 390. +
Rear Bumper Lower Spoiler Deband		<del>1200(SW)</del> 780(SW)
Rear Bumper Lower Cover Deband		285.40 /
Rear Bumper Lower Cover Clips. <sup>new</sup>		30(SW) /
Rear End Panel Dented		585.10. /
Rear End Panel Top Garnish. Deband		98.40. /
Rear End Panel Top Garnish Clips. <sup>new</sup>		20(SW) /
Rear End Panel Sealant <sup>new</sup>		60(SW) +
Rear End Panel Antenna Sensor	} <sup>NIPT</sup> <sub>new</sub>	60.20. +
Rear End Panel Buzzer.		85.20 +.

SMM2883H.

Reverse Sensor Damaged	<del>280(SN)</del> 200(SN)
Tailgate Dented	1100
Tailgate Lock Damaged	182.50
Tailgate Weatherstripe. ut	188.90
Tailgate Outer Garnish. NH M	325.40 x
Tailgate Outer Garnish. Clips. NH M	20(SN) x
Tailgate Inner Trim Board cracked	285.60
Tailgate Inner Trim Board clips. NH M	30(SN)
Tailgate Reflector x 02 ut	413.2 x 2 = 826.40
Tailgate Glass Moulding. NH M	120.40
Tailgate Glass Sealant. NH M	60(SN)
Honda Logo NH M	30.40 x
Vezel Emblem. NH M	45.90
Rear Camera. NH M	480(SN) x
Rear Fender Inner Trim Board x 02 <sup>RH</sup> cracked	305.2 x 2 = 610.40
Rear Fender Inner Trim Board clips. NH M	<del>60(SN)</del> 30(SN)
Taillamp x 02 cracked.	474.6 x 2 = 949.20

416648

SMM 2883H.

Spere Tyre Panel Top Board } 306.60. X  
 Tools Tray Sponge. } 285.40. X  
 Reer Exhaust pipe. } 598.60. X

5293.20 S.N. 1180  
 4634.56

Panel Beating	<del>1200</del>	<del>800</del>	\$700
Spray Painting.	<del>1200</del>	800	
Wiring.	<del>50</del>	30	
To remove reverse sensor	<del>100</del>	<del>50</del>	\$30
To remove rear camera.	<del>100</del>	<del>50</del>	\$30
To remove rear video recorder	<del>150</del>	60	
To remove upholstery.	<del>150</del>	50	
To spray tuff coat.	<del>150</del>	60	2070.
To transfer tailgate hitting.	<del>180</del>	120	
To remove tailgate g/l/s)	<del>150</del>	X	
To <del>remove</del> exhaust pipe.			\$7,724.56

total: ~~7884.56~~  
 Hs: ~~6.3k~~  
 \$6,200/-  
 05 Days

6.3k

LK Rano Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental y item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature: