

E M Solution Pte Ltd

160 Sin Ming Drive #03-18/19, Sin Ming Autocity
Singapore 575722

Tel: 64560226 Fax: 64584500

GST Reg. No: 201016308K

Not

Not withair
V1 Lamp & 1100k
Putty After Pain
4days


ESTIMATE

Mr **Wong Ee Moh**
Blk 116 Lorong 2, Toa Payoh, #05-144
Singapore 310116

Date : 8th July 2022

Veh No : **FL 538G**
Make/Model : **Vespa ExcelP150XE**
Chassis No : **V LX1T3019950**
Date of Acc : **26.06.22**
TP Veh No : **SLX 4711L**

S/No	Qty	Description	Unit Price	Amount
Materials (Nett)				
1	1 pc	Frt Wheel Mudguard		\$ Bu 250.00 ✓
2	1 pc	Headlamp		\$ CM 200.00 ✓
3	1 pc	Headlamp Housing		\$ CM 350.00 ✓
4	1 pc	Rear View Mirror RH		\$ Rd 90.00 ✓
5	1 pc	Frt Handle Brake Lever RH		\$ D17 25.00 ✓
6	1 pc	Frt Frame Rubber RH		\$ CM 80.00 ✓
7	1 pc	Footboard Garnish RH		\$ Sn 55.00 X
8	1 pc	Frt Fender Signal Lamp RH		\$ Lt 25.00 ✓
9	1 pc	Rear Wheel Cover RH		\$ R 120.00 X
10	1 pc	Rear Wheel Cover Indicator Lamp RH		\$ L 55.00 X
11	1 pc	Rear Helmet Box		\$ Rd/Lt 90.00 ✓
12	1 pc	Frt No Plate		\$ B 35.00 2012
			10/	Parts Total : \$ 1,375.00
Labour				
1		To remove & rearrange electrical wirings, check lightings		\$ 30.00 15/
2		To remove, repair & replace damaged bodyparts and where consistent to the accident.		\$ 400.00 180/
3		Putty and respray painting on affected portions.		\$ 300.00 200/
				Labour Total : \$ 730.00
				Total Parts & Labour : \$ 2,105.00


for E M Solution Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: