

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241

Fax: (65) 6741 7276

RCB No: 53231488C

GST Reg No: 53231488C

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date : 30/06/2022

30/06/2022

TP Chim.
Xiao Tony.

Estimated repair cost for vehicle no: SJB3888G MERCEDES BENZ E200

CHASSIS: WDD2120482A3498

S/N	Qty	Items	U/price	Amount
1	1	RH FRONT DOOR <i>Dented</i>	\$2,445.00	\$2,445.00 1850
2	1	RH FRONT DOOR HINGE <i>2</i>	\$101.00	\$101.00 +
3	1	RH FRONT DOOR CHECKER <i>green</i>	\$69.00	\$69.00 +
4	1	RH FRONT DOOR LOCK	\$469.00	\$469.00 +
5	1	RH FRONT DOOR OUTER HANDLER <i>green</i>	\$342.00	\$342.00 +
6	1	RH FRONT DOOR OUTER CHROME MOULDING <i>green</i>	\$221.00	\$221.00 +
7	1	RH FRONT DOOR WEATHER STRIPE <i>new</i>	\$289.00	\$289.00 +
8	1	RH FRONT DOOR POWER WINDOW MOTOR <i>green</i>	\$796.00	\$796.00 +
9	1	RH FRONT DOOR POWER WINDOW MOTOR GEAR	\$365.00	\$365.00 +
10	1	RH FRONT DOOR INNER TRIM BOARD <i>new</i>	\$1,264.00	\$1,264.00 +
11	1	RH FRONT DOOR OUTER CHANNEL <i>new</i>	\$241.00	\$241.00 +
12	1	RH FRONT DOOR MIRROR <i>new</i>	\$1,745.00	\$1,745.00 890
13	1	RH FRONT DOOR MIRROR COVER <i>Reps</i>	\$126.00	\$126.00 +
14	1	RH FRONT DOOR MIRROR SIGNAL LAMP <i>new</i>	\$164.00	\$164.00 +
15	1	RH REAR DOOR <i>Dented</i>	\$2,567.00	\$2,567.00 1780
16	1	RH REAR DOOR HINGE <i>green</i>	\$101.00	\$101.00 +
17	1	RH REAR DOOR CHECKER	\$69.00	\$69.00 +
18	1	RH REAR DOOR LOCK <i>new</i>	\$460.00	\$460.00 +
19	1	RH REAR DOOR OUTER CHROME MOULDING <i>new</i>	\$189.00	\$189.00 +
20	1	RH REAR DOOR WEATHER STRIPE <i>new</i>	\$315.00	\$315.00 +
21	1	RH REAR DOOR POWER WINDOW MOTOR <i>new</i>	\$796.00	\$796.00 +
22	1	RH REAR DOOR POWER WINDOW MOTOR GEAR <i>new</i>	\$365.00	\$365.00 +
23	1	RH REAR DOOR INNER TRIM BOARD <i>new</i>	\$1,264.00	\$1,264.00 +
24	1	RH REAR DOOR OUTER CHANNEL <i>new</i>	\$241.00	\$241.00 +
25	1	RH ROCKER PANEL GARNISH <i>new</i>	\$845.00	\$845.00 692
26	1	RH REAR FENDER <i>Reps</i>	\$2,354.00	\$2,354.00 +
27	1	REAR WINDSCREEN GLASS WITH MOULDING <i>new</i>	\$1,498.00	\$1,498.00 +
28	1	RH REAR LOWER ARM <i>But</i>	\$562.00	\$562.00 485
29	1	RH REAR UPPER ARM <i>But</i>	\$384.00	\$384.00 303
30	1	RH REAR SHOCK ABSORBER <i>new</i>	\$689.00	\$689.00 +

SJB3888G MERCEDES BENZ E200

31	1	RH REAR KNUCKLER ARM <i>Dmd</i>	\$746.00	\$746.00 <i>✓</i>
32	1	RH REAR WHEEL BEARING <i>Dmd</i>	\$304.00	\$304.00 <i>✓</i>

7989
7158-10

TOTAL :	\$22,386.00
LESS 10 %	\$2,238.60
SUB-TOTAL :	\$20,147.40

S/N	Qty	ITEMS / SPECIAL NETT	U/price	Amount
1	1	RH FRONT DOOR INNER TRIM BOARD CLIPS <i>gmp</i>	\$120.00	\$120.00 <i>x</i>
2	1	RH REAR DOOR INNER TRIM BOARD CLIPS <i>m</i>	\$120.00	\$120.00 <i>x</i>
3	1	RH ROCKER PANEL GARNISH CLIPS <i>m</i>	\$100.00	\$100.00 <i>30</i>
4	1	RH REAR SPORT RIM <i>at</i>	\$850.00	\$850.00 <i>453</i>
5	1	REAR WINDSCREEN GLASS SEALANT <i>ne m</i>	\$150.00	\$150.00 <i>x</i>

480

TOTAL:	\$1,340.00
TOTAL PARTS :	\$21,487.40

Labour charges

- 1 LABOUR FOR PANEL BEATING
- 2 LABOUR FOR SPRAYPAINTING
- 3 LABOUR FOR REMOVE & TRANSFER BOTH RH DOOR FITTING
- 4 WIRING CHECK
- 5 TO APPLY TUFF COATING/RUST PROOF ACCIDENT AREAS
- 6 LABOUR FOR REMOVE & RENEW RH REAR UNDERCARRIAGE
- 7 TO CONDUCT WHEEL ALIGNMENT
- 8 LABOUR FOR REMOVE & REFIX REAR WINDSCREEN GLASS

1730

\$1,800.00	<i>600</i>
\$1,600.00	<i>800</i>
\$600.00	<i>160</i>
\$80.00	<i>30</i>
\$300.00	<i>60</i>
\$400.00	<i>x</i>
\$150.00	<i>80</i>
\$150.00	<i>x</i>

\$5,080.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

acknowledged by Repairer

Total:- \$26,567.40

total: 9409.10

1/s: 7-SK

7-SK

04/09



PEOPLES AUTO TRADING
BLK 3007 UBI ROAD 1 #01-400
TEL 6741 4646



COMPUTERIZED ALIGNMENT SPECIALISTS

CUSTOMER	SM	DATE	Jul 4, 2022 10:17:03 AM
FIRST NAME			
LICENSE NO.	SJB 3888 G		
MILEAGE	162869		
MAKE	CUSTOM	MODEL	MERCEDES BENZ E CLASS
NOTES			

Front Wheel	SPECS				DIAGNOSIS				ADJUSTMEN			
	min	prv	max	Δ	L	total	R	Δ	L	total	R	Δ
TOTAL TOE	0.00	1.00	2.10			2.50				2.50		
PARTIAL TOE	0.00	0.50	1.00		0.80		1.70		0.50		2.00	
SET BACK	---	---	---			-0°02"				-0°02"		
CAMBER	-1°00"	0°00"	1°00"		-1°36"		-1°08" 0°30"		-0°36"		-1°08" 0°30"	
CASTER	5°30"	6°30"	7°30"		6°30"		6°26" 0°04"		6°30"		6°26" 0°04"	
KING-PIN	---	---	---		13°16"		13°10" 0°06"		13°16"		13°10" 0°06"	
INCLANGLE	---	---	---		12°38"		12°02"		12°38"		12°02"	
Toe-out on turns	---	---	---		---		---		---		---	
STEERING IN	---	---	---		---		---		---		---	
STEERING OUT	---	---	---		---		---		---		---	

Rear Wheel	SPECS				DIAGNOSIS				ADJUSTMEN			
	min	prv	max	Δ	L	total	R	Δ	L	total	R	Δ
TOTAL TOE	0.00	2.10	4.20			4.80				4.80		
PARTIAL TOE	0.00	1.00	2.10		3.30		1.50		3.30		1.50	
SET BACK	---	---	---			0°00"				0°00"		
CAMBER	-2°00"	-1°00"	0°00"		-1°14"		-2°20" 1°04"		-1°14"		-2°20" 1°04"	
THRUST ANGLE	-0°08"	0.00	0°08"			0°08"				0°08"		