

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 05 Jul 2022)

Parts: 144 TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SHA8182E/05/07/2022 15:41

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*BONNET	25.00	0.00	BT *1,117.93 FL ✓
2	1		*BONNET HINGE LH	25.00	0.00	BT *87.70 FL ✓
3	1		*BONNET HINGE RH	25.00	0.00	BT *87.70 FL ✓
4	1		*BONNET LOCK	25.00	0.00	un *132.60 FL ✓
5	1		*FRT FENDER LH	25.00	0.00	BT *1,111.93 FL ✓
6	1		*FRT FENDER SIDE BRACKET LH	25.00	0.00	Rm *77.00 FL ✓
7	1		*HEADLAMP ASSY LH	25.00	0.00	un *2,637.60 FL ✓
8	1		*HEADLAMP ASSY RH	25.00	0.00	X *2,637.60 FL ✓
9	1		*HEADLAMP PANEL UPPER	25.00	0.00	BT *364.98 FL ✓
10	1		*HEADLAMP PANEL LH	25.00	0.00	BT *240.10 FL ✓
11	1		*FRT BUMPER ASSY	25.00	0.00	de *586.18 FL ✓
12	10		*FRT BUMPER CLIPS	25.00	0.00	un *22.00 FL ✓
13	1		*RADIATOR GRILLE	25.00	0.00	un *438.00 FL ✓
14	1		*FRT BUMPER LOWER GRILLE	25.00	0.00	de *198.18 FL ✓
15	1		*FRT BUMPER TOW COVER LH	25.00	0.00	un *28.38 FL ✓
16	1		*FRT BUMPER TOW COVER RH	25.00	0.00	un *28.38 FL ✓
17	1		*FRT BUMPER BEAM	25.00	0.00	BT *812.89 FL ✓
18	1		*FRT BUMPER BEAM STAY BRACKET LH	25.00	0.00	Rm *138.00 FL ✓
19	1		*FRT BUMPER BEAM STAY BRACKET RH	25.00	0.00	Rm *138.00 FL ✓
20	1		*BONNET EMBLEM	25.00	0.00	un *198.18 FL ✓
21	1		*RADIATOR ASSY	25.00	0.00	BT *1,841.80 FL ✓
22	1		*RADIATOR FAN GRILLE	25.00	0.00	Rm *632.40 FL ✓
23	1		*RADIATOR FAN MOTOR	25.00	0.00	Rm *661.30 FL ✓
24	1		*CONDENSOR	1374.02 25.00	0.00	? BT *2,924.20 FL ✓
25	1		*FRT NUMBER PLATE	0.00	0.00	BT *50.00 F ✓
26	1		*FRT NUMBER PLATE GARNISH	25.00	0.00	de *99.00 FL ✓
27	1		*FRT FENDER EMBLEM LH	25.00	0.00	un *86.50 FL ✓
28	1		*FRT BUMPER SPONGE	25.00	0.00	un *78.80 FL ✓
29	1		*FRT BUMPER FOG LAMP LH	25.00	0.00	Rm *85.10 FL ✓
F=Franchise part. L=ListItemDisc.						
*Support front bumper side 82.30						
Air cleaner 446.50						
Battery SN 220.						
- List Item Discount on L Items (\$\$)						
Sub Total (\$\$)						
Total Parts (\$\$)						

ComfortDelGro Engineering Pte Ltd/SHA8182E/05/07/2022 15:41. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

12601.45
25% - 9451.08
SN 270.
9721.08

3:42 PM

Repairer Estimates

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	PANEL BEATING	New	✓ 200 1,400.00
2	SPRAYPAINT	New	✓ 250 900.00
3	CHECK WIRING	→ New	30 50.00
4	TUFF KOTE	New	✓ 30 50.00
5	RENEW / REFIX AIR CON AND REFILL GAS	New	✓ 100 120.00
6	TOWING FEE	New	✓ 60.00
Gross Labour Cost (S\$)			1670 2,580.00

ComfortDelGro Engineering Pte Ltd/SHA8182E/05/07/2022 15:41. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tanphie 92425844 9721.08
 WP 6/7/22 @ 4:30pm 11
 P/P Resurvey before permit 1670
 Tanphie @ Khantokan 11,402.08
 3-4 days. 04 days
 #

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: