

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22006450/GCQ2**Date:** 12/01/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNA00021512200

Claimant Vehicle No : SMM7903B **Insured Vehicle No :** GBD4125C

Date of Loss: 17/06/2022 Nature of Claim: TP Claim No: SNM22D204667/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMM7903B**

Make & Model: TOYOTA PRIUS PLUS, 1.8 (A) Engine No: 2ZR0D45252

Reg. Date: 15/07/2019 (Man. Year: 2019) Chassis No: JTDZS3EU90J040196

Colour: Brown Odometer: 244672 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16

Front Left Side: Firenza 6 mm Rear Left Side: Firenza 6 mm

Front Right Side: Firenza 6 mm Rear Right Side: Firenza 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,942.00	942.50	4,999.50	84.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,040.00	810.00	1,230.00	60.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,982.00	1,752.50	6,229.50	78.04
Approved Total (Overridden) (S\$)		1,400.00		
(S\$)	7,982.00	1,400.00	6,582.00	82.46
+ GST 8.00/8.00% (S\$)	638.56	112.00	526.56	82.46
Nett Amount (S\$)	8,620.56	1,512.00	7,108.56	82.46

INSPECTION

Date of Assignment: 05/07/2022

Date Inspected: 05/07/2022 Inspected At: My Car Consultant Pte Ltd (Jalan Lam Huat) (HQ)
60 Jalan Lam Huat, Carros Centre #05-21
Singapore 737869

Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Jan 2023)
Parts:	M1-MPV	TOYOTA PRIUS PLUS 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMM7903B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Cut	879.00 FL	*786.00 FL
2	1		*FRT BUMPER SIDE RETAINER RH	Not Necessary	45.00 FL	*- FL
3	1		*FRT BUMPER DAYLIGHT COVER RH	Not Necessary	52.00 FL	*- FL
4	1		*FRT BUMPER DAYLIGHT RH	Broken	312.00 FL	*312.00 FL
5	1		*FRT BUMPER BRACKET RH	Not Necessary	52.00 FL	*- FL
6	1		*HEADLAMP RH	Not Necessary	2,257.00 FL	*- FL
7	1		*WIPER WASHER TANK	Not Necessary	345.00 FL	*- FL
8	1		*FRONT FENDER RH	Repair	698.00 FL	*- FL
9	1		*FRONT FENDER EMBLEM HYBRID RH	Necessary	52.00 FL	*52.00 FL
10	1		*FRONT FENDER COWLING RH	Not Necessary	198.00 FL	*- FL
11	1		*FRT LOWER ARM RH	Not Necessary	581.00 FL	*- FL
12	1		*FRT KNUCKLE ARM RH	Not Necessary	587.00 FL	*- FL
13	1		*FRT WHEEL BEARING RH	Not Necessary	198.00 FL	*- FL
14	1		*SET FRT BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
15	1		*FRT FENDER INNERSHIELD CLIP FRT LH	Not Necessary	50.00 FS	*- FS
16	1		*FRONT WHEEL HUB CAP RH	Scratched	100.00 FS	*50.00 FS
17	1		*FRONT TYRE RH	Not Necessary	250.00 FS	*- FS
18	1		*FRONT SPORTS RIM LH	Not Necessary	800.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	7,506.00	1,230.00
- List Item Discount on L Items 25.00/25.00% (\$)	1,564.00	287.50
Total Parts (\$)	5,942.00	942.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK WIRING	New	100.00	30.00
2	R+R FRONT UNDERCARRIAGE	New	400.00	0.00
3	WHEEL ALIGNMENT	New	100.00	80.00
4	R+R FRT FENDER QUARTER GLASS RH	New	120.00	0.00
5	REALIGN HEADLAMP	New	120.00	0.00
6	KNOCK	New	600.00	300.00
7	SPRAY	New	600.00	400.00
Gross Labour Cost (S\$)			2,040.00	810.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >