Note: This document has not been finalised. LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: India International Insurance Pte Ltd

64 Cecil Street #04-00 IOB Building Singapore 049711 From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25

Paya Ubi Industrial Park Singapore 408933

Attn: Priya Date: 10 Mar 2023

Preliminary Advice

Vehicle No : SNB5395B Accident Date : 20/06/2022

Make : TOYOTA NOAH Policy No. : D18MFL0003414-02

Assignment Date : 06/07/2022 Excess : \$\$0.00 Date of Inspection : 06/07/2022 Est. Duration of Repair : 8

Inspection At : COMFORTDELGRO ENGINEERING PTE LTD (BRADDELL)

205 BRADDELL ROAD SINGAPORE 579701

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	18,449.00
-----------------------------	------	-----------

Revised Amount :S\$ 10,971.75 (Inclusive of Supplementary 2)

Check Items (Estimated) :S\$ 0.00

Total :S\$ 10,971.75

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

 Pre-Accident Value
 :S\$ 160,000.00

 COE / PARF Rebate
 :S\$ 59,429.00

Salvage Value :S\$

Margin for Repair :S\$ 100,571.00

Remarks

(X)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kind	lly
	let us have your authorisation.	

) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments : KINDLY APPROVE ON SUPPLEMENTARY.