

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 05 Jul 2022)
 Parts: M1-MPV TOYOTA NOAH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: ComfortDelGro Engineering Pte Ltd/SNB5395B/05/07/2022 18:27
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No. Qty Part No. Particulars

			%Disc	%Depr	Amount	
1	1	*FRT LH FENDER 911.20	25	0.00	1,116.00 F	✓
2	1	*FRT LH FENDER INNER SHIELD	25	0.00	181.00 F	✓
3	8	*FRT LH FENDER INNER SHIELD CLIP	25	0.00	44.00 F	✓
4	1	*FRT LH FENDER QUARTER GLASS	25	0.00	633.00 F	XX
5	1	*FRT LH FENDER QUARTER GLASS SEALANT	0	0.00	40.00 FS	XX
	1	*FRT LH DOOR	25	0.00	1,744.00 F	✓
	1	*FRT LH DOOR HINGE TOP	25	0.00	104.00 F	✓
8	1	*FRT LH DOOR HINGE LOWER	25	0.00	118.00 F	✓
9	1	*FRT LH DOOR CHECKER	25	0.00	196.00 F	XX
10	1	*LH WING MIRROR ASSY	25	0.00	1,011.00 F	✓
11	1	*FRT LH DOOR OUTER MOULDING	25	0.00	111.00 F	✓
12	1	*FRT LH DOOR FRAME STICKER (VERTICAL FRT)	25	0.00	30.00 F	✓
13	1	*FRT LH DOOR FRAME STICKER (VERTICAL REAR)	25	0.00	59.00 F	✓
14	1	*FRT LH DOOR FRAME STICKER TOP	25	0.00	42.00 F	✓
15	1	*FRT LH DOOR WEATHER STRIP	25	0.00	329.00 F	XX
16	1	*FRT LH DOOR LOCK MECHANISM	25	0.00	596.00 F	✓
17	1	*FRT LH DOOR LOWER INNER RUBBER SEAL	25	0.00	96.00 F	XX
18	1	*FRT LH DOOR GLASS	25	0.00	633.00 F	✓
19	1	*FRT LH DOOR GLASS SOLAR FILM	0	0.00	200.00 FS	✓ 100% in
20	1	*FRT LH DOOR GLASS RUN CHANNEL	0	0.00	274.00 FS	XX
21	1	*FRT LH DOOR OUTER HANDLE	25	0.00	415.00 F	✓
22	1	*FRT LH DOOR HANDLE SENSOR	25	0.00	25.00 F	✓
23	1	*FRT LH DOOR HANDLE SEAL 1	25	0.00	18.00 F	✓
	1	*FRT LH DOOR HANDLE SEAL 2	25	0.00	18.00 F	✓
25	1	*LH CENTER PILLAR OUTER	0.00	0.00	304.00 F	XX
26	1	*LH PILLAR CHASSIS STICKER	0	0.00	60.00 FS	XX
27	1	*LH SLIDING DOOR 1594.	25	0.00	1,927.00 F	✓
28	1	*LH SLIDING DOOR OUTER HANDLE	25	0.00	157.00 F	✓
29	1	*LH SLIDING DOOR PRESS BUTTON SENSOR	0.00	0.00	161.00 F	✓
30	1	*LH SLIDING DOOR FRT VERTICAL SENSOR MOULDING	25	0.00	1,372.00 F	✓
31	1	*LH SLIDING DOOR GLASS MOULDING	25	0.00	105.00 F	✓
32	1	*LH SLIDING DOOR VERTICAL BLACK STICKER	25	0.00	51.00 F	✓
33	1	*LH SLIDING DOOR TOP BLACK STICKER	25	0.00	50.00 F	✓
34	1	*LH SLIDING DOOR LOCK MECHANISM	0	0.00	254.00 FS	XX
35	1	*LH SLIDING DOOR GLASS REGULATOR	25	0.00	337.00 F	XX
36	1	*LH SLIDING DOOR BODY WEATHER STRIP	0	0.00	109.00 FS	XX
37	1	*LH SLIDING DOOR AUTO DR MOTOR	25	0.00	4,664.00 F	XX
38	1	*LH SLIDING DOOR LOWER ROLLER	25	0.00	140.00 F	XX

F=Franchise part, S=SpcNett.

Supp
 - LH Sliding door Garnish
 - wing mirror outer cover LH
 - Door handle cover.

Sub Total (\$\$)
 - List Item Discount on L Items (\$\$)

Total Parts (\$\$)

17,724.00
 4,080.50

13,643.50

ComfortDelGro Engineering Pte Ltd/SNB5395B/05/07/2022 18:27. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRclaim&fuseaction=gen_docview&caseid=1110316&doctype=REPEST&corole=1&... 2/4

810528.15

9350.20

EWK80

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 21 Jul 2022)
Parts: M1-MPV TOYOTA NOAH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: ComfortDelGro Engineering Pte Ltd/SNB5395B/21/07/2022 10:26
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT LH DOOR HANDLE INNER BRACKET	CM 25	0.00	*144.00 F ✓
2	1		*REAR LH SLIDING DOOR HANDLE INNER BRACKET	CM 25	0.00	*167.00 F ✓
3	1		*REAR LH SLIDING DOOR HANDLE RUBBER SEAL 1	stock available M 25	0.00	*18.00 F ✓
4	1		*REAR LH SLIDING DOOR HANDLE RUBBER SEAL 2	M 25	0.00	*18.00 F ✓
5	1		*LH FRT FENDER INNER COVER	CM 25	0.00	*118.00 F ✓
franchise part.						
Sub Total (S\$)						465.00
- List Item Discount on L Items (S\$)						116.25
Total Parts (S\$)						348.75

ComfortDelGro Engineering Pte Ltd/SNB5395B/21/07/2022 10:26. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

to auth. by ref by TM

Estimates on Miscellaneous Items

Qty	Particulars	Amount
Miscellaneous Items		
1	1 OD/TP Case (Insurer)	11.00
Sub Total (\$\$)		11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO CUT ,WELD ON LH CENTER PILLAR,JACK,STRAIGHTEN ON FRT LH A PILLAR,LH REAR SIDE PANEL,REPLACE DAMAGE PARTS AND REALIGN AFFECTED AREAS	New	1,800.00
2	TO PUTTY,RESPRAY ON LH FRT FENDER,A PILLAR,FRT LH DOOR ,CENTER PILLAR,SLIDING DOOR,LH SIDE REAR PANEL,LH WINGMIRROR AND EFFECTED AREAS	New	1,600.00
3	TO TRANSFER LH DOOR PART TO NEW DOOR	New	150.00
	TO TRANSFER LH SLIDING DOOR PARTS TO NEW DOOR	New	250.00
5	TO REMOVE INTERIOR UPHOLSTERY TO ASSIST REPAIR AND REFIT	New	120.00
6	CHECK LIGHTING AND WIRING	New	30.00
7	TO REPROGRAM LH SLIDING DOOR AFTER RENEW	New	300.00
Gross Labour Cost (\$\$)			4,250.00

ComfortDelGro Engineering Pte Ltd/SNB5395B/05/07/2022 18:27. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: