

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTERGO Insurance Pte. Ltd.
8 Temasek Boulevard, #04-01 Suntec Tower Three
Singapore 038988**Our File No:** CS/EGI22006455/GQCM4
Date: 17/04/2023**REFERENCE**Insured/Claimant: ALEXANDRA HO CHAI HOONG Policy No: DMPG21014497
Date of Loss: 18/06/2022 Nature of Claim: OD Claim No: CDMPG22001185**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SMR3785A**
Make & Model: AUDI Q3, 1.4 TFSI (A) Engine No: CZD886626
Reg. Date: 31/12/2019 (Man. Year: 2019) Chassis No: WAUZZZF30L1015435
Colour: Grey Odometer: 47169 km
Engine Capacity: 1395 cc
Market Value/New Car Price: S\$160,000.00
Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes**CONDITION OF TYRES**Front Tyre Size: 235/55R17 Rear Tyre Size: 235/55R17
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,466.00	4,422.00	44.00	0.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	613.00	453.00	160.00	26.10
Paintwork Labour	332.38	332.38	0.00	0.00
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,411.38	5,207.38	204.00	3.77
+ GST 7.00/8.00% (S\$)	378.80	416.59	-37.79	-9.98
Nett Amount (S\$)	5,790.18	5,623.97	166.21	2.87

INSPECTIONDate of Assignment: 06/07/2022 Present Location: Vin's Motor Pte Ltd (Sin Ming)
VIN'S MOTOR PTE LTD
160 SIN MING DRIVE #03-03
Date Inspected: 06/07/2022 Inspected At: SIN MING AUTO CITY
SINGAPORE 575722
Estimated Period of Repair: 4.0 days**Adjuster:** XING GUO QIANG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 17 Apr 2023)
Parts: M1-SUV	AUDI Q3 1.4 TFSI (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SMR3785A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*Clips (WCP)	Necessary	20.00 F	*20.00 F
2	1	NA	*FRONT BUMPER SPOILER (WCP)	Broken	220.00 F	*220.00 F
3	1	NA	*H/LAMP WASHER VALVE (WCP)	Broken	130.00 F	*130.00 F
4	1	NA	*L/BUMP CLOSING PART (WCP)	Broken	20.00 F	*20.00 F
5	1	NA	*L/F AIR GUIDE GRILLE (WCP)	Cracked	90.00 F	*90.00 F
6	1	NA	*L/F BUMPER COVER (WCP)	Cut	520.00 F	*520.00 F
7	1	NA	*L/F BUMPER LWR MLDG (WCP)	Broken	60.00 F	*60.00 F
8	1	NA	*L/F WING EXTENSION (WCP)	Deformed	160.00 F	*160.00 F
9	1	NA	*LEFT HEADLAMP ASSY (WCP)	Cut	2,800.00 F	*2,800.00 F
10	1	NA	*LH Nozzle Gun Cover (WCP)	Not Necessary	40.00 F	*- F
11	1	NA	*SUNDRY PARTS (NPA)	Not Necessary	0.00 F	*- F

F=Franchise part.

Sub Total (\$\$)	4,060.00	4,020.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	406.00	402.00
Total Parts (\$\$)	4,466.00	4,422.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	Total Paint Labour	New	256.50	256.50
2	Total Paint Materials	New	75.88	75.88
Labour Items				
3	Total Panel/Mechanical Labour	New	613.00	453.00
			Gross Labour Cost (\$\$)	785.38

Report was unsubmitted during this print-out.

< END OF ESTIMATES >