

Vehicle Damage Assessment Report for [SMR3785A]

Estimate Created: 13/04/2023 15:30 by Insurlogic 4 (Insurlogic_Pte_Ltd)

Owned: 13/04/2023 15:40 by Insurlogic 4 (Insurlogic_Pte_Ltd)

General Information

Insurance Company	ERGO	Claim Number
Claim Type	OD	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Audi	Model	Q3
Engine Type			
License Plate Number	SMR3785A	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- FINAL REVIEW BASE ON INFORMATION PROVIDED BY LKK:
CONCLUDED THE COST OF REPAIR AT \$5,207.38 WITH 4 WORKING
DAYS

Insurlogic 4 (13/04/2023 15:40)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
FRONT BUMPER CLIPS		1	20.00	10.00 %	22.00
FRONT BUMPER SPOILER		1	220.00	10.00 %	242.00
HEADLAMP WASHER VALVE		1	130.00	10.00 %	143.00
FRONT BUMPER COVER		1	20.00	10.00 %	22.00
LEFT FRONT AIR GUIDE GRILLE		1	90.00	10.00 %	99.00
LEFT FRONT BUMPER COVER		1	520.00	10.00 %	572.00
LEFT FRONT BUMPER LOWER MOULDING		1	60.00	10.00 %	66.00
LEFT FRONT WING EXTENSION		1	160.00	10.00 %	176.00
LEFT HEADLAMP		1	2800.00	10.00 %	3,080.00
Parts Subtotal					4,422.00

Labor

Replace/RnR

Description	Type	Cost	Markup/Disc %	Price
PANEL BEATING	RnR	453.00	0.00 %	453.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price	
SPRAY PAINTING	Full spray	332.38	0.00 %	332.38	
Labor Rate	S\$ 50 / Hour	General Labor Subtotal		453.00	
				Paint Labor Subtotal	332.38
				Labor Subtotal	785.38

Summary

Repair Cost	5,207.38
Discount(0 %)	(0.00)
	5,207.38
Excess	(0.00)
GST(0.00 %)	0.00
Grand Subtotal	5,207.38