

**Vin's Motor Pte Ltd**  
**#03-03, Sin Ming AutoCity, 160 Sin**  
**Ming Drive**  
**575722**

**Vin's**

**Insurer Reference:**  
**Repairer Reference: OD/072022/5508**  
**Date calculated: 04/07/2022 5:57 PM**

**Full Report**  
**Registration: SMR3785A**  
**Printed: 04/07/2022 5:57 PM**

### Summary Information

#### Claim

|                        |                 |                   |                        |
|------------------------|-----------------|-------------------|------------------------|
| Location:              | Singapore (SG)  | Work Provider:    | ERGO Insurance Pte Ltd |
| Printed by:            | Khong Keng Leng | Currency:         | SGD                    |
| Claim Reference:       |                 | Date of Incident: | 18/06/22               |
| Estimated Repair Time: |                 | Hire Car Start:   |                        |
| Actual Repair Days:    |                 | Hire Car End:     |                        |

### Vehicle Details

#### Vehicle

|                     |                   |
|---------------------|-------------------|
| Manufacturer:       | AUDI              |
| Model:              | Q3                |
| Sub Model:          | BASE MODEL        |
| Model Sheet Number: | 00 Q3 01          |
| Registration:       | SMR3785A          |
| VIN number:         | WAUZZZF30L1015435 |
| Odometer:           |                   |

#### Model Specs

|                      |                      |                      |                      |
|----------------------|----------------------|----------------------|----------------------|
| FROM 09.2019         | R/DOOR MIRROR W/ANG  | L/MIRROR CONVEX      | ELEC CHILD SEC LOCK  |
| FRONT BRAKE 312 X 25 | TAILGATE POWER LOCK  | AUTO AIR CON         | ULTRASONIC PARK SYS  |
| KEYLESS ENTRY        | FOLD/DIPPING MIRROR  | AUTO DIPPING MIRROR  | AUDI VIRTUAL COCKPIT |
| MMI NAVIGATION PLUS  | LED HEADLAMP         | HIGH BEAM ASSISTANT  | LED-REAR LAMPS       |
| HEADLAMP WASHERS     | LIGHT-/RAIN SENSOR   | SURROUND CAMERAS     | EQUIP LEATH/IMIT LEA |
| SEAT BELT ALARM      | STORAGE PACKAGE      | MULTIF LEAT ST/WHEEL | ST/WHEEL SWITCH ROCK |
| SMOKER EQUIPMENT     | RADIO FREQ 434MHZ    | FRONT ASSIST         | INTERIOR LAMP PACK   |
| ELECT LUMBAR ADJUST  | FRONT CENTRE ARMREST | REAR CENTRE ARMREST  | L/ELEC ADJUST SEAT   |
| R/ELEC ADJUST SEAT   | ALTERNATOR 140A      | HOT /SUPER HOT LAND  | 1395CCM 110KW        |
| ACTIVE CARBON FILTER | EMISSION STD EURO 6+ | S-TRONIC 6-SPEED     | SPEED LIMITER        |
| SELECT DRIVE         | TYRES 235/55 VR 18   | WHEELS 7J X 18 ALLOY | ONLINE SERVICES      |
| ROOF RACK ALLOY      | TRIM PACK ALUMINIUM  | TWO COAT METALLIC    | PREPARE OFF VEHICLE  |

**LKK Auto Consultants hence notify**  
**the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to information
- Third party claims are handled on a "No Prejudice" basis
- No illegal trade in parts
- Supplier of parts is subject to change and is subject to the insurance company

Acknowledged

Signature

Date

## Vehicle Condition

### Vehicle Status

Pre-Accident Damage:

Date of Inspection:

### Damage Areas

All ☐  
Underbody ☐



## Tyres Condition

| Tyre Brand | Tread (Left Middle),<br>mm | Tread (Left Outer),<br>mm | Tread (Left Inner),<br>mm | Tread (Right Inner),<br>mm | Tread (Right Outer),<br>mm | Tread (Right<br>Middle), mm | Condition |
|------------|----------------------------|---------------------------|---------------------------|----------------------------|----------------------------|-----------------------------|-----------|
|------------|----------------------------|---------------------------|---------------------------|----------------------------|----------------------------|-----------------------------|-----------|

| Spare Tyre Brand | Tread (Spare), mm |
|------------------|-------------------|
|------------------|-------------------|

## Labour

| Code         | Description                                                                                                                                                                | Time Base 10 WU/h | Price = 45.00 SGD/h |           |
|--------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------|---------------------|-----------|
|              |                                                                                                                                                                            |                   | WU                  | Price SGD |
| 01 50 00 ZAX | GFS / GUIDED FUNCTION<br>(READ OUT FAULT MEMORY)                                                                                                                           |                   | 3.0                 | 13.50     |
| 44 05 19 00  | R + R LEFT FRONT WHEEL                                                                                                                                                     |                   | 2.0                 | 9.00      |
| 66 16 19 50  | R + R L/F WHEELHOUSE SHELL<br>(WHEEL REMOVED)                                                                                                                              |                   | 3.0                 | 13.50     |
| 63 29 19 00  | R + R FRONT BUMPER COVER                                                                                                                                                   |                   | 10.0                | 45.00     |
| 63 29 55 54  | RENEW L/FR BUMPER COVER<br>(BUMPER COVER REMOVED)<br>INCLUDES: RAD GRILLE ,DETACH/ATTACH<br>FRT SPOILER,<br>SPOILER, AIR GUIDE GRILLE<br>AND WASHER JET AND SYSTEM SENSORS |                   | 12.0                | 54.00     |
| 66 03 19 50  | R + R FRONT BUMPER SPOILER                                                                                                                                                 |                   | 2.0                 | 9.00      |
| 94 15 19 50  | R + R L/HEADLAMP<br>(FRONT BUMPER COVER REMOVED)<br>DOES NOT INCLUDE: ADJUST HEADLAMP                                                                                      |                   | 1.0                 | 4.50      |
| 94 15 55 50  | RENEW L/HEADLAMP (REMOVED)                                                                                                                                                 |                   | 1.0                 | 4.50      |
| 63 17 19 50  | R + R LOCKING PART L BUMPER FR                                                                                                                                             |                   | 1.0                 | 4.50      |

| Code         | Description                          | WU    | Price SGD |
|--------------|--------------------------------------|-------|-----------|
| 66 19 20 01) | R + R FRONT WING FLARINGS (ADD/WORK) | 2.0   | 9.00      |
| 92 60 19 50) | R + R WINDSCREEN WASHER TANK         | 1.0   | 4.50      |
| 66 19 19 01) | R + R L/F WING EXTENSION             | 2.0   | 9.00      |
| 24 25 19 00  | R + R AIR CLEANER                    | 4.0   | 18.00     |
| 90 83 15 00  | SURROUND CAMERA ADJUST               | 3.0   | 13.50     |
| 91 63 15 60  | ADJUST FRONT RADAR SENSOR            | 1.0   | 4.50      |
| 94 15 16 50  | ADD WORK FOR H-LAMP LEVEL CONTROL    | 1.0   | 4.50      |
| 0340         | FRT BUMPER SUPPORT REPAIR            | 10.0* | 45.00     |
| 0741         | L/F WING REPAIR                      | 15.0* | 67.50     |
| 1001         | Programming Headlamp                 |       | 280.00*   |

|                                  |            |           |        |
|----------------------------------|------------|-----------|--------|
| <b>Labour Cost</b>               | <b>Hrs</b> | <b>WU</b> |        |
| <b>Panel / Mechanical Labour</b> | 7.40       | 74.0      | 333.00 |
| <b>Alignment</b>                 |            |           | 280.00 |
| <b>Fixed Rate</b>                |            |           |        |
| <b>Total of Labour</b>           |            |           | 613.00 |

## Paint

| Paint Work | SYSTEM AZT                          | Time Basis 10 WU/h |
|------------|-------------------------------------|--------------------|
| Code       | Description - TWO COAT METALLIC     | WU Price SGD       |
|            | L/F BUMPER COVER NEW PART PAINT K1R | 5.0                |
|            | L/F WING REPAIR PAINTING >50%       | 18.0               |
|            | FRT BUMPER SUPPORT SURFACE PAINT    | 4.0                |

## Paint Material Per Part

| Code | Description                         | Price SGD |
|------|-------------------------------------|-----------|
| 0281 | L/F BUMPER COVER NEW PART PAINT K1R | 15.25     |
| 0741 | L/F WING REPAIR PAINTING >50%       | 20.54     |
| 0340 | FRT BUMPER SUPPORT SURFACE PAINT    | 2.49      |

|                                |             |           |                  |
|--------------------------------|-------------|-----------|------------------|
| <b>Labour Cost - Paint</b>     | <b>Hrs</b>  | <b>WU</b> | <b>Price SGD</b> |
| Factor                         | 45.00 SGD/h |           |                  |
| Time Paint                     |             | 27.0      |                  |
| Preparation Main Work Metal    | 2.50        | 25.0      | 112.50           |
| Preparation Comp. Work Plastic | 0.50        | 5.0       | 22.50            |
| <b>Total</b>                   | 10 WU/h     | 5.70      | 57.0             |
|                                |             |           | 256.50           |

|                                     |                  |
|-------------------------------------|------------------|
| <b>Material Cost - Paint</b>        | <b>Price SGD</b> |
| New Part Painting - Plastic K1R     | 15.25            |
| Repair Painting                     | 20.54            |
| Surface-/Blend Paint                | 2.49             |
| Material-constant Metal Preparation | 28.60            |
| Material-constant Plastic           | 9.00             |
| <b>Total</b>                        | 75.88            |

## Spare Parts

prices as at 2015-09-02/23

| Code                     | Description          | Part Number   | Part Source             | Price SGD |
|--------------------------|----------------------|---------------|-------------------------|-----------|
| 1000                     | Clips / <i>Mc</i>    | Bumper        | Original                | 20.00     |
| 0391                     | FRONT BUMPER SPOILER | 83A 807 061   | Original                | 220.00    |
|                          |                      | 4W3           |                         |           |
| 0361                     | H/LAMP WASHER VALVE  | 83A 955 101   | Original                | 130.00    |
| 0319                     | L/BUMP CLOSING PART  | 83A 807 095   | Original                | 20.00     |
| 0297                     | L/F AIR GUIDE GRILLE | 83A 807 681   | 9B9 Original <i>CRA</i> | 90.00     |
| 0281                     | L/F BUMPER COVER     | 83A 807 107 D | Original <i>CR</i>      | 520.00    |
|                          |                      | GRU           |                         |           |
| 0285                     | L/F BUMPER LWR MLDG  | 83A 807 925   | 9B9 Original <i>BR</i>  | 60.00     |
| 0883                     | L/F WING EXTENSION   | 83A 853 717   | Original <i>RR</i>      | 160.00    |
|                          |                      | 4W3           |                         |           |
| 0561                     | LEFT HEADLAMP ASSY   | 83A 941 773 A | Original <i>CR</i>      | 2,800.00  |
| 1002                     | LH Nozzle Gun Cover  | LH Nozzle Gun | Original                | 40.00     |
|                          |                      |               |                         | 0.00      |
| f: OEM Parts             |                      |               |                         |           |
| n: Non-OEM Parts         |                      |               |                         |           |
| u: Used parts            |                      |               |                         |           |
| <b>Savings</b>           |                      |               |                         |           |
| <b>Subtotal</b>          |                      |               |                         | 4,060.00  |
| <b>Addition(+10.00%)</b> |                      |               |                         | 406.00    |
| <b>Total</b>             |                      |               |                         | 4,466.00  |

## Final Calculation

|                                       | SGD      | SGD      |
|---------------------------------------|----------|----------|
| <b>Parts</b>                          |          |          |
| Addition(+10.00%)                     | 4,060.00 |          |
| <b>Total Parts</b>                    | 406.00   | 4,466.00 |
| <b>Labour Time Base 10 WU/h</b>       |          |          |
| Total 74.0 WU X 45.00 SGD/h           |          |          |
| Alignment                             | 333.00   |          |
| Fixed Rate                            | 280.00   |          |
| <b>Total of Labour</b>                |          | 613.00   |
| <b>Paint Work Time Base 10 WU/h</b>   |          |          |
| Labour Cost 57.0 WU X 45.00 SGD/h     |          |          |
| Material Cost                         | 256.50   |          |
| <b>Total Paint Including Material</b> | 75.88    | 332.38   |
| <b>Repair Cost Excludes GST</b>       |          | 5,411.38 |
| GST (+7.0%)                           |          | 378.80   |
| <b>Repair Cost Included GST</b>       |          | 5,790.18 |

## Comments

\* - USER SUPPLIED DATA  
 NN - NO MANUFACTURERS CODE EXISTS  
 ) - WU PARTIAL INCL IN OTHER POSITIONS

## Assessment Note

No assessment notes entered.