

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ERGO Insurance Pte. Ltd.
8 Temasek Boulevard, #04-01 Suntec Tower Three
Singapore 038988

Our File No: CS4/EGI22006462/GVY3M4**Date:** 17/08/2022**REFERENCE**

Insured/Claimant:	MY LITTLE PROPS HOUSE	Policy No:	DMCG22005560
Date of Loss:	03/07/2022	Nature of Claim:	OD
		Claim No:	CDMCG22001320

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBD7178E		
Make & Model:	TOYOTA HIACE, 3.0 D DX (M)	Engine No:	1KD2491343
Reg. Date:	09/04/2015 (Man. Year: 2014)	Chassis No:	KDH2010161214
Colour:	Silver	Odometer:	0 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	S\$35,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Poor	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Average

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 0 mm	Rear Right Side:	Bridgestone 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	0.00	0.00	0.00	
- Excess (\$\$)	500.00	0.00	500.00	100.00
Nett Amount (\$\$)	-500.00	0.00	-500.00	100.00

INSPECTION

Date of Assignment:	06/07/2022 Present Location:	Forza Autohaus Pte Ltd (HQ) Forza Autohaus Pte Ltd (HQ) No.39 Woodlands Close, #01-34/35, Mega@Woodlands Singapore 737856
Date Inspected:	07/07/2022 Inspected At:	
Estimated Period of Repair:	0.0 days	

Adjuster: XING GUO QIANG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

Market Value :	\$35,000.00
OMV :	\$27,943.00
PARF Rebate (1) :	\$0
Quota Premium Paid :	\$16,724.00
COE Rebate (2) :	\$4,599.00
Total Rebate (1) + (2) = :	\$4,599.00

The total amount incurred will be Market Value \$35,000.00 minus Total Rebate \$4,599.00 = \$30,401.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Aug 2022)
Parts:	213	TOYOTA HIACE 3.0 D DX (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBD7178E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >