

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.  
8 Temasek Boulevard  
#04-01 Suntec Tower Three  
Singapore 038988

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Senthilan Dillen Selvarajoo

Date: 08 Jul 2022

## **Preliminary Advice**

Vehicle No	: GBD7178E	Accident Date	: 03/07/2022
Make	: TOYOTA HIACE	Policy No.	: DMCG22005560
Assignment Date	: 06/07/2022	Excess	: S\$500.00
Date of Inspection	: 07/07/2022	Est. Duration of Repair	: 0
Inspection At	: FORZA AUTOHAUS PTE LTD (HQ) NO.39 WOODLANDS CLOSE, #01-34/35, MEGA@WOODLANDS SINGAPORE 737856		

## **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	TOTAL LOSS
Revised Amount	:S\$	TOTAL LOSS
Check Items (Estimated)	:S\$	0.00
Total	:S\$	0.00

Lump Sum Repair	:S\$
-----------------	------

## **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	35,000.00
COE / PARF Rebate	:S\$	4,599.00
Salvage Value	:S\$	
Margin for Repair	:S\$	30,401.00

## **Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( X ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Vehicle recommended Total Loss