



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN: CYNTHIA		Ref: CC4/ASM22006465/Upa3q2 Date: 27/04/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 2534C	Veh. Inspected	SMN 7194A
Policy No.	P2465679	Coverage (\$)	0.00
Claim No.	S2M045ZI	Excess (\$)	0.00
Assign From		Assign Date	06/07/2022
2. Vehicle Particulars & Condition			
Make & Model	AUDI A4 1.8T FSI MU	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	WAUZZZ8K8AA055537	Colour	WHITE
Odometer	132669 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/50 R17	BRIDGESTONE	6 mm
L/H Front Tyre	225/50 R17	BRIDGESTONE	6 mm
R/H Rear Tyre	225/50 R17	BRIDGESTONE	6 mm
L/H Rear Tyre	225/50 R17	BRIDGESTONE	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	04/07/2022	Inspection Date	07/07/2022
Survey held at	NINETEEN AUTOWERKS PTE. LTD. 15 KAKI BUKIT ROAD 4 #01-53 BARTLEY BIZ CENTRE SINGAPORE 417807		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	