

AUTOMOBILE HUB ENTERPRISE

1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY@KAKI BUKIT

SINGAPORE 417883

Tp Somp
Xiao Chen

Page No. 1

Vehicle No. PC8371X

TOYOTA HIACE COMMUTER

GDH2232001483

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR ADJUSTMENT
	PARTS (LIST ITEMS)			
1	FRONT BUMPER <i>Distorted</i>		589.60	✓
2	FRONT BUMPER SIDE HOLDER <i>2nd</i>		89.40	✓
3	FRONT BUMPER FOG LAMP COVER <i>Rehd</i>		97.40	✓
4	FRONT BUMPER REINFORCEMENT <i>Best.</i>		412.40	✓
5	HEADLAMP LH <i>cut</i>		2326.70	✓
6	FRONT LH CORNER PANEL <i>Dehd</i>		408.10	✓
7	FRONT LH CORNER PANEL MIRROR <i>missing</i>		973.20	✓
8	BONNET <i>Revs</i>		825.30	x
9	BONNET HINGE @79.30 <i>new</i>		158.60	x
10	FRONT WINDSCREEN MOULDING <i>new</i>		129.80	x
11	WIPER PANEL GARNISH <i>new</i>		368.90	x
12	FRONT LH STEP PANEL <i>Dehd</i>		401.40	✓
13	FRONT LH STEP PANEL GARNISH <i>cut</i>		288.20	✓
14	FRONT LH DOOR <i>Distorted</i>		1658.80	✓
15	FRONT LH DOOR LOCK <i>new</i>		342.80	x
16	FRONT LH DOOR WEATHERSTRIPE <i>cut</i>		283.20	✓
17	FRONT LH DOOR INNER TRIM BOARD <i>cut</i>		645.10	✓
18	FRONT LH DOOR HINGE @115.20 <i>Dehd</i>		230.40	✓
19	FRONT LH DOOR CHECK <i>new</i>		95.40	x
20	FRONT LH DOOR OUTER HANDLE <i>cut</i>		163.50	✓
21	FRONT LH DOOR GLASS <i>cut</i>		440.90	✓
22	FRONT LH DOOR GLASS OUTER MOULDING <i>cut</i>		195.40	✓
23	FRONT LH DOOR GLASS REGULATOR GEAR <i>2nd</i>		309.20	✓
24	FRONT LH DOOR GLASS REGULATOR MOTOR <i>new</i>		510.40	x
25	FRONT LH DOOR WING MIRROR <i>missing</i>		693.70	✓
26	FRONT LH DOOR OUTER PILLAR <i>Dehd</i>		855.30	✓
27	FRONT LH DOOR INNER PILLAR <i>Revs</i>		453.90	x
28	FRONT LH DOOR WIRE HARNESS <i>snapped</i>		541.30	✓
29	FRONT LH DOOR WIRE HARNESS COVER <i>2nd</i>		98.40	✓
30	FRONT LH DOOR REAR PANEL <i>Dehd</i>		581.60	✓
31	FUEL COVER <i>Revs</i>		80.70	x
32	SLIDING DOOR LH <i>Dehd</i>		1611.70	✓
33	SLIDING DOOR LOCK LH <i>new</i>		289.40	x
34	SLIDING DOOR OUTER HANDLE LH <i>cut</i>		170.40	✓
35	SLIDING DOOR GLASS LH <i>cut</i>		695.40	✓
36	REAR LH BODY PANEL <i>Revs</i>		1817.90	x
37	REAR LH BODY PANEL GLASS (FRONT) <i>cut</i>		509.50	✓
38	REAR LH BODY PANEL GLSS (REAR)		894.10	✓
39	REAR LH BODY PANEL RAIL TRACK <i>new</i>		325.10	x
40	TAILLAMP LH <i>new</i>		361.50	x
41	FRONT SHOCK ABSORBER @298.40 <i>RH Best</i>		596.80	298.40
42	FRONT LOWER ARM @466.10 <i>RH Best</i>		932.20	466.10
43	FRONT KNUCKLE ARM @566.40 <i>RH Best</i>		1132.80	566.40
44	FRONT WHEEL HUB C/W BEARING @315.10 <i>RH Best</i>		630.20	315.10
45	ADBLUE TANK <i>cut</i>		585.40	✓

18395.70
13796.77

SPECIAL NETT ITEMS

- 1 FRONT BUMPER CLIPS *new*
- 2 FRONT LH STEP PANEL GARNISH CLIPS *new*
- 3 FRONT LH WHEEL RIM *new*
- 4 FRONT LH WHEEL RIM COVER *new*
- 5 FRONT LH TYRE *new*
- 6 FRONT WINDSCREEN SEALANT *new*
- 7 FRONT LH DOOR INNER TRIM BOARD CLIPS *new*
- 8 FRONT LH DOOR SPEAKER *cracked*
- 9 FRONT LH DOOR VISOR *cracked*
- 10 SLIDING DOOR GLASS SEALANT *new*
- 11 EXCURSION BUS STICKER *new*
- 12 REAR LH BODY PANEL GLASS SEALANT (FRONT) *new*
- 13 REAR LH BODY PANEL GLASS SEALANT (REAR) *new*
- 14 REAR LH WHEEL RIM *new*
- 15 REAR LH WHEEL RIM COVER *missing*
- 16 REAR LH TYRE *new*
- 17 FRONT RH WHEEL RIM *new*
- 18 FRONT RH WHEEL RIM COVER *cracked*
- 19 FRONT RH TYRE *new*

Total Parts

less 25%

25211.80

6302.95

18908.85

25%

980

30.00

20.00

280.00

~~200.00~~

250.00

60.00

30.00

~~280.00~~

~~150.00~~

40.00

50.00

40.00

60.00

280.00

~~200.00~~

250.00

280.00

~~200.00~~

250.00

2950.00

AUTOMOBILE HUB ENTERPRISE

1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY@KAKI BUKIT
SINGAPORE 417883

Page No. 2

Vehicle No. PC8371X

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$)	OUR ASSESSMENT (\$)
	LABOUR		
1	PANEL BEATING	2000.00 1500	
2	SPRAY PAINTING	1600.00 1400	
3	WIRING	100.00 30	
4	TO APPLY TUFF COAT	200.00 120	
5	TO REMOVE UPHOLSTERY	150.00 60	
6	TO TRANSFER FRONT DOOR FITTINGS	150.00 80	
7	TO REMOVE DASHBOARD	350.00 X	
8	TO REMOVE FRONT WINDSCREEN	180.00 X	
9	TO TRANSFER SLIDING DOOR FITTINGS	150.00 40	
10	TO REMOVE SLIDING DOOR GLASS	100.00 60	
11	TO REMOVE REAR BODY PANEL GLASSES	150.00 120	
12	TO PERFORM WHEEL ALIGNMENT	150.00 80	
13	TO REMOVE FRONT UNDERCARRIAGES	650.00 220	
14	TOWING FEES	150.00 60	3770
	Labour Total :	6080.00	
	TOTAL (PARTS & LABOUR):	27938.85	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 18546.77

A/S: 148K

11 Days