



SC AUTO INDUSTRIES (S) PTE LTD

51 Senoko Road, Singapore 758133

T 65 6758 2222

F 65 6257 6931

E sales@scauto.com.sg

scauto.com.sg

Co. Reg. No. 199800107D

ESTIMATE Bill

GST Reg. No: 19-9800107D

Date: 7/7/2022

Our Case Ref. SC22/07/086/4KB-TP

Accident Date 7/7/2022

M/S KW BUS SERVICE
Blk 764a, Woodlands Circle, #10-304,
SINGAPORE 731764
Insured KW BUS SERVICE
Policy DMB1SNW00012602004

Damaged Vehicle No: CB7053E

S/no	Description	QTY	Price	Disc	Amount
<u>Replaced Parts</u>					
1	SIDE MIRROR ASSY LH <i>repair</i>	1 PC	\$1,980.00	-	\$1,980.00
<u>Labour Charges</u>					
1	LABOUR TO CHECK WIRENESS.	1	\$650.00	- <i>300</i>	\$650.00
2	LABOUR TO REMOVE, REPAIR AND REINSTALL SIDE MIRROR ASSY LH, FRT FIBER CAP ASSY AND FRT BUMPER.	1	\$3,000.00	- <i>1280</i>	\$3,000.00
3	LABOUR TO RESPRAY SIDE MIRROR ASSY LH, FRT FIBER CAP ASSY, FRT BUMPER.	1	\$2,500.00	- <i>960</i>	\$2,500.00
4	LABOUR TO CARRY OUT DIAGNOSTIC CHECK	1	\$250.00	- <i>X</i>	\$250.00

Ram
Hf 90010068
3 days
P/P
12/07/22 @ 1420
Rosy after you

Sub Total

\$ 8,380.00

Authorised Signature