



SC AUTO INDUSTRIES (S) PTE LTD

51 Senoko Road, Singapore 758133
T 65 6758 2222 F 65 6257 6931
E sales@scauto.com.sg
scauto.com.sg

Co. Reg. No. 199800107D

M/S KW BUS SERVICE
Blk 764a, Woodlands Circle, #10-304,
SINGAPORE 731764
Insured KW BUS SERVICE
Policy DMB1SNW00012602004

ESTIMATE Bill

GST Reg. No: 19-9800107D
Date: 7/7/2022
Our Case Ref. SC22/07/086/4KB-TP
Accident Date 7/7/2022

Damaged Vehicle No: CB7053E

S/no	Description	QTY	Price	Disc	Amount
Replaced Parts					
1	SIDE MIRROR ASSY LH <i>repair cut</i>	1 PC	\$1,980.00	-	\$1,980.00 1600
Labour Charges					
1	LABOUR TO CHECK WIRENESS.	1	\$650.00	- 300	\$650.00
2	LABOUR TO REMOVE, REPAIR AND REINSTALL SIDE MIRROR ASSY LH, FRT FIBER CAP ASSY AND FRT BUMPER.	1	\$3,000.00	- 1280	\$3,000.00
3	LABOUR TO RESPRAY SIDE MIRROR ASSY LH, FRT FIBER CAP ASSY, FRT BUMPER.	1	\$2,500.00	- 960	\$2,500.00
4	LABOUR TO CARRY OUT DIAGNOSTIC CHECK	1	\$250.00	- 11X	\$250.00
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date: 1600 2540 <u>4140</u> <i>Resur</i> <i>Hp 90010068</i> <i>3 days</i> <i>P/P</i> <i>12/01/22 @ 1420</i> <i>Resy after spr</i>					
Sub Total					S 8,380.00

Authorised Signature