



Your Ref : YP5670C
Our Ref : SC22/07/086/4KB-TP (CB7053E)

9 September 2022

LONPAC INSURANCE BHD
Attn: Motor Claims Department

WITHOUT PREJUDICE
BY E-MAIL ONLY

Dear Sir / Mdm,

ACCIDENT INVOLVING CB7053E & YP5670C ON 28/06/2022

We are instructed by the owner of CB7053E to claim damages against your insured in connection with a road traffic accident involving our client's motor vehicle no. CB7053E and motor vehicle no. YP5670C driven by your insured at the material time.

We are instructed that the accident was caused by your insured's negligence and/or management of his motor vehicle. As a result of the accident, our client's motor vehicle was damaged and our clients have been put to loss and expenses, particulars of which are as follows:

1.	Costs of Repair (Incl. GST)	\$	4,429.80	
2.	Loss of Use	\$	2,250.00	(\$450x 5 days Including weekend and PRI)
3.	GIA Search Fee	\$	2.00	
	Total	\$	6,681.80	

Please note that our **bus is under PRIVATE HIRE, NOT PRIVATE NON-HIRE**, thus, not listed in the NIMA Benchmark Rates, we need higher LOU to close.

Please note that you should send us an acknowledgement of receipt of this letter of demand by e-mail to claims@scauto.com.sg within seven (7) days of your receipt of this letter and revert with an offer not later than fourteen (14) days of this letter. If we do not hear from you, we will submit the claim via our solicitors.

Thank You.

Yours faithfully,

Raymond Ting
Claim Executive
D +65 6571 9958

SC Auto Industries (S) Pte Ltd
51 Senoko Road, Singapore 758133
T 65 6758 2222 F 65 6257 6931

scauto.com.sg
Singapore • Hong Kong • Myanmar
Co. Reg No: 199800107D

Global Standards, Local Support



SC AUTO INDUSTRIES (S) PTE LTD

51 Senoko Road, Singapore 758133

T 65 6758 2222

F 65 6257 6931

E sales@scauto.com.sg

scauto.com.sg

Co. Reg. No. 199800107D

M/S KW BUS SERVICE
Blk 764a, Woodlands Circle, #10-304,
SINGAPORE 731764
Insured KW BUS SERVICE
Policy DMB1SNW00012602004

Damaged Vehicle No: CB7053E

Final Bill

GST Reg. No: 19-9800107D
Date: 8/9/2022
Our Case Ref. SC22/07/086/4KB-TP
Accident Date 7/7/2022

S/no	Description	QTY	Price	Disc	Amount
<u>Replaced Parts</u>					
1	SIDE MIRROR ASSY LH	1 PC	\$1,600.00	-	\$1,600.00
<u>Labour Charges</u>					
1	LABOUR TO CHECK WIRENESS.	1	\$300.00	-	\$300.00
2	LABOUR TO REMOVE,REPAIR AND REINSTALL SIDE MIRROR ASSY LH, FRT FIBER CAP ASSY AND FRT BUMPER.	1	\$1,280.00	-	\$1,280.00
3	LABOUR TO RESPRAY SIDE MIRROR ASSY LH, FRT FIBER CAP ASSY, FRT BUMPER.	1	\$960.00	-	\$960.00
Sub Total					\$ 4,140.00
GST (7%)					\$ 289.80
Total Amount					\$ 4,429.80

Authorised Signature

INSURER ENQUIRY


Find

insurer

Vehicle reg. no.

YP5670C

Date of Accident

28/06/2022 

Reset

% RESULT & RECEIPT

TP Insurer Enquiry

Insurance **Lonpac Insurance Bhd**Period of Insurance **09/03/2022 - 08/03/2023**Requested By **Hamimah Bte Jamaludin (SC ...**Requested Date **04/07/2022 14:31**

Payment details

Request Amount: **S\$1.87**GST Amount: **S\$0.13**Total Amount Due (GST Inclusive): **S\$2**

General Insurance Association

Records Management Centre

GST Registration No: **M400017735**