

Performance Motors

BMW Dealer



Final Report

Estimate No. : **b1 62347**
Date Estimated : **30/06/2022**
Prepared By : **Yap Mee Key**

Page No. :

- ESTIMATE REPAIR FOR -

LIM WHEE KONG
10 PRINSEP LINK
#11-21

SINGAPORE 187948

- ACCOUNT - 135

China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKB9788K	WBA22DP0309K93529	15/06/2022	X3 xDrive20i	1715

DESCRIPTION	ORIGINAL PRICE		NETT
To replace engine hood and front grille include knocking out dents caused by the accident	850.00	0.00	850.00
To respray engine hood	1,298.00	0.00	1,298.00
To carry out body cavity preservation. (Per panel).	112.00	0.00	112.00
To check electrical wiring system and ligitings at the front section for proper function	168.00	0.00	168.00
Sundries.	80.00	0.00	80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
BONNET	1,929.95	1.00	0.00	1,929.95
FRT GRILLE (BASIS)	265.75	1.00	0.00	265.75

SUPPLEMENTARY ITEMS

Total Labour :	2,508.00
Total Parts :	2,195.70
Total Labour & Parts :	4,703.70
Deduction for Excess :	
Total Repair Costs less Excess:	4,703.70
GST @7%:	329.26
Grand Total :	5,032.96

Performance Motors Limited.

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269
Co Reg No. 197401559W

