

Cheek Part 3/8/22



Performance Motors Limited

A Sime Darby Motors Company
 Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
 Toll-Free Number (1800-2255269)

303, Alexandra Road
 Sime Darby Performance Centre
 Singapore 159941
 Fax. 64747770

280, Kampong Arang Road
 East Coast Centre
 Singapore 438180
 Fax. 63449773

315, Alexandra Road
 Sime Darby Business Centre
 Singapore 159944
 Fax. 64796601 (AfterSales)
 64796624 (Motorrad)

Steve (LKK)
 7/9/22, 3992

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Page No. : 1 of 4

Estimate No. : b1 62347
 Date Estimated : 30/06/2022
 Prepared By : Yap Mee Key

3 days

- ESTIMATE REPAIR FOR -

LIM WHEE KONG
 10 PRINSEP LINK
 #11-21

SINGAPORE 187948

- ACCOUNT - 135
 China Taiping Insurance (S) Pte Ltd
 3 Anson Road
 #16-00 Springleaf Tower
 Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKB9788K	WBA22DP0309K93529	15/06/2022	X3 xDrive20i	15

DESCRIPTION	VALUE
To replace engine hood and make good front bumper.	850 / 1,700.00
To respray engine hood and front bumper.	1298 / 2,336.00
To carry out body cavity preservation. (Per panel).	112 / 118.00
To check electrical system.	168 / 177.00
Sundries.	80.00
Total Labour 1:	4,411.00

DESCRIPTION	QTY	PRIC	VALUE
BONNET	1	1,929.95	1,929.95
EXPANDING RIVET	10	0.50	5.00
Grill front	1	265.75	265.75
AIR FLAPS TOP	1	291.55	291.55
AIR DUCT RADIATOR TOP	1	107.50	107.50
FRT ENGINE HOOD SEALING	1	34.55	34.55
Total Parts :			2,634.30

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Resurvey is on a "Without Prejudice" basis
- Modification(s) is allowed
- Defective item(s) must be resurveyed and
- To final approval from Insurance Company



Acknowledged by Repairer

Signature:

Labour 1	:	4,411.00
Parts	:	2,634.30
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	493.17
Grand Total	:	7,538.47

**** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY ****
**** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE ****