LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: India International Insurance Pte Ltd

64 Cecil Street #04-00 IOB Building Singapore 049711 From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Sherini Pillai Date: 08 Jul 2022

Preliminary Advice

Vehicle No : SMN2442S Accident Date : 16/06/2022

Make : PEUGEOT 5008 Policy No. : D20MFL0000326 01

Assignment Date : 07/07/2022 Excess : \$\$0.00 Date of Inspection : 07/07/2022 Est. Duration of Repair : 04

Inspection At : KUM CHEW MOTOR WORKSHOP

Point of Impact / General Description of Damages

Parts claimed are not consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,243.95
Revised Amount	:S\$	3,333.85
Check Items (Estimated)	:S\$	730.10
Total	:S\$	4,063.95

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

 Pre-Accident Value
 :S\$ 109,000.00

 COE / PARF Rebate
 :S\$ 56,986.00

Salvage Value :S\$

Margin for Repair :S\$ 52,014.00

Remarks

()	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
		Kindly let us have your authorisation.

- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ($\,$ X $\,$) Other comments : Suggest to conduct investigation for this case.

Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part

prices and labour cost.