

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/AIS22006487/UCY3E2

**Date:** 29/07/2022

### REFERENCE

Handling Insurer: Allianz Insurance Singapore Pte. Ltd. Policy No: SP2000640415  
**Claimant Vehicle No :** FZ4854T **Insured Vehicle No :** SFB128J  
Date of Loss: 01/07/2022 Nature of Claim: TP Claim No: 202222005524KC

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FZ4854T**  
Make & Model: HONDA TA200, 197cc PHANTOM (M) Engine No: TA200E0024752  
Reg. Date: 26/07/2005 (Man. Year: 2004) Chassis No: TA2000024752  
Colour: Black Odometer: 98853 km  
Engine Capacity: 197 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 90-80-17 Rear Tyre Size: 130-90-17  
Front Left Side: Maxxis 5 mm Rear Left Side: Maxxis 5 mm  
Front Right Side: 0 mm Rear Right Side: 0 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	630.00	499.50	130.50	20.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	300.00	180.00	120.00	40.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>930.00</b>	<b>679.50</b>	<b>250.50</b>	<b>26.94</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>500.00</b>		
<b>Nett Amount (S\$)</b>	<b>930.00</b>	<b>500.00</b>	<b>430.00</b>	<b>46.24</b>

### INSPECTION

Date of Assignment: 07/07/2022  
Date Inspected: 07/07/2022 Inspected At: FT FASTTRACK (HQ)  
25 KAKI BUKIT RD 4 #01-77 S417800  
Singapore 417800  
Estimated Period of Repair: 2.0 days

**Adjuster:** MARCUS CHUA

**Manager:** CELINE FONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 28 Jul 2022)	
Parts:	N/A	HONDA TA200 197cc PHANTOM (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FZ4854T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HANDLE BAR	Not Necessary	110.00 FL	*- FL
2	1		*MIRROR (RH)	Scratched	70.00 FL	*70.00 FL
3	1		*BRAKE LEVER (LH)	Scratched	40.00 FL	*40.00 FL
4	1		*SIGNAL LAMP FRONT (RH)	Cut	65.00 FL	*65.00 FL
5	1		*FRONT FENDER	Cut	110.00 FL	*110.00 FL
6	1		*BRAKE PEDAL	Bent	90.00 FL	*90.00 FL
7	1		*FOOTREST FRONT (RH)	Damaged	75.00 FL	*75.00 FL
8	1		*EXHAUST PROTECTOR	Dented	105.00 FL	*105.00 FL
9	1		*HANDLE BAR BALANCER (RH)	Not Necessary	35.00 FL	*- FL
F=Franchise part. L=ListItemDisc.						
Sub Total (\$\$)					700.00	555.00
- List Item Discount on L Items 10.00/10.00% (\$\$)					70.00	55.50
Total Parts (\$\$)					630.00	499.50

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TRANSPORT FEE	New	50.00	0.00
2	LABOUR CHARGE	New	250.00	180.00
<b>Gross Labour Cost (S\$)</b>			<b>300.00</b>	<b>180.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >