

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22006495/UYA3Q2**Date:** 17/07/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800103907
Claimant Vehicle No :	SFW999B	Insured Vehicle No :	SMD7244S
Date of Loss:	28/06/2022	Nature of Claim:	TP
		Claim No:	6881204339SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFW999B	Engine No:	03916004N52B30AF
Make & Model:	BMW 730LI, 3.0 (A)	Chassis No:	WBAHN22010DE96397
Reg. Date:	23/03/2006 (Man. Year: 2005)	Odometer:	142637 km
Colour:	Grey		
Engine Capacity:	2996 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	265/30Z R22	Rear Tyre Size:	295/25Z R22
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,204.99	1,206.97	998.02	45.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	630.00	300.00	330.00	52.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,834.99	1,506.97	1,328.02	46.84
Approved Total (Overridden) (S\$)		1,200.00		
(S\$)	2,834.99	1,200.00	1,634.99	57.67
+ GST 7.00/7.00% (S\$)	198.45	84.00	114.45	57.67
Nett Amount (S\$)	3,033.44	1,284.00	1,749.44	57.67
+ Loss of Use (2.0 x S\$100.00/day) (S\$)		200.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,486.00		
Global Sum Settlement (S\$)		1,400.00		

INSPECTION

Date of Assignment:	07/07/2022		
Date Inspected:	07/07/2022	Inspected At:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Estimated Period of Repair:	2.0 days		

Adjuster: MARCUS CHUA**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR MIRROR ASSY N/S	Damaged / Shorted	1,270.50 F	*1,270.50 FL
2	1		*FRONT DOOR MIRROR OUTER COVER N/S	Repair	122.59 F	*- FL
3	1		*FRONT DOOR MIRROR GLASS N/S	Not Necessary	811.90 F	*- FL
					Sub Total (\$)	2,204.99 1,270.50
					- List Item Discount on L Items 0.00/5.00% (\$)	0.00 63.53
					Total Parts (\$)	2,204.99 1,206.97

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DIAGNOSTIC & REPROGRAMME SYSTEM }	New	180.00	180.00
2	LABOUR FOR DISMANTLE & REPLACED PARTS }	New	250.00	0.00
3	TO PUTTY & SPRAY PAINTING	New	200.00	120.00
Gross Labour Cost (S\$)			630.00	300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >