

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMZ 1984M

lty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			(Ψ)
	REAR UPPER BUMPER	DEFORMED	808.45	800.4
1	REAR LOWER BUMPER	BROKEN	406.10	808.4
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	509.10	406.10
1	REAR BUMPER TOW HOOK COVER	MISSING	69.00	60.00
1	REAR BUMPER L/H SIDE RETAINER	NECESSARY	65.30	69.00
1	REAR BUMPER R/H SIDE RETAINER	NECESSARY	65.30	65.30
1	SET REAR BUMPER CLIPS	NECESSARY	35.00	65.30 35.00
	REAR END (OUTER) PANEL	TO REPAIR SEE LABOUR	543.10	35,00
	LESS 25% DISCOUNT	, *	_	-362,29
			2,501.35	1,086.86
2	REVERSE SENSOR @\$365.10 (SN)	NOT WORKING	730.20 730.20	200.00
	LABOUR	77	730.20	200.00
- [1	TO PANEL BEAT AND RENEWAL OF ALL NECESSARY DAMAGED BODY PARTS. INCLUSIVE OF THE REPAIR OF REAR END (OUTER) PANEL.	9" 3"- 1	1,000.00	400.00
l	TO REMOVE AND REINSTALL REAR BOOT JPHOLSTERY.	NOT NECESSARY	120.00	-
-	TO REMOVE AND REINSTALL REVERSE SENSOR.	2	140.00	60.00
	TO APPLY ANTI-RUST.	NOT NECESSARY	60.00	00.00
	TO PUTTY AND SPRAY-PAINT OF AFFECTED AREAS.		800.00	400.00
		8	2,120.00	860.00
	GRAND TOTAL		, . = 3,30	000.00

Report Ref No. CS1/SPF22006499/Gcy3e2

NOTES: THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$1,700-\$2,000

XING GUO QIANG

M.MATAI, AMSAE-A

(TO ITS PRE-ACCIDENT CONDITION)

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.