

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

ZHENG SHIXI
BLK 613 BUKIT PANJANG RING ROAD
#19-852
SINGAPORE 670613

Contact : 91378759

TP Chiam.

Veron.

TAX INVOICE

Repair Code : CLM17280

Date in : 05/07/2022

Vehicle Num. : SMS1969U

Model : HONDA FIT 1.3GF CVT

Chassis/Eng# : GK31354510/L13B1465439

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Dented</i>	1	551.50	✓ 551.50
REAR BUMPER CENTER BLACK MOULDING <i>cracked</i>	1	85.40	✓ 85.40
REAR BUMPER GRILLE COVER L/R <i>cracked</i>	2	48.10	✓ 96.20
REAR BUMPER SIDE RETAINER L/R <i>cracked</i>	2	11.50	✓ 23.00
REAR END PANEL <i>Dented</i>	1	505.40	✓ 505.40
REAR END PANEL ANTENNA SENSOR <i>cracked</i>	1	107.40	✓ 107.40
REAR END PANEL BUZZLE SENSOR <i>cracked</i>	1	98.40	✓ 98.40
REAR END PANEL INNER TOP GARNISH <i>cracked</i>	1	60.80	✓ 60.80
REAR FENDER INNER TRIM GARNISH L/R <i>LH cracked</i>	2	199.70	<i>199.70</i> ✓ 399.40
REAR FLOOR PANEL <i>Repair</i>	1	683.30	+ 683.30
REAR FLOOR PANEL SPONGE TRAY <i>torn</i>	1	127.30	✓ 127.30
REAR FLOOR PANEL TOP BOARD COVER <i>Dented</i>	1	189.90	✓ 189.90
REAR TAILGATE <i>Dented</i>	1	1071.10	<i>950</i> 1,071.10
REAR TAILGATE 'FIT' EMBLEM <i>new</i>	1	68.00	✓ 68.00
REAR TAILGATE DAMPER L/R <i>2 new</i>	2	106.80	+ 213.60
REAR TAILGATE HINGES L/R <i>2 new</i>	2	33.20	+ 66.40
REAR TAILGATE INNER PULL HANDLE <i>new</i>	1	18.50	+ 18.50
REAR TAILGATE INNER RUBBER SIDE GUIDE STOPPER L/R <i>new new</i>	2	15.50	X 31.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

ZHENG SHIXI
BLK 613 BUKIT PANJANG RING ROAD
#19-852
SINGAPORE 670613

Contact : 91378759

TAX INVOICE

Repair Code : CLM17280

Date in : 05/07/2022

Vehicle Num. : SMS1969U

Model : HONDA FIT 1.3GF CVT

Chassis/Eng# : GK31354510/L13B1465439

REAR TAILGATE INNER TRIM BOARD <i>could</i>	1	63.70	✓	63.70
REAR TAILGATE MECHANISM LOCK <i>Daugd</i>	1	78.90	✓	78.90
REAR TAILGATE NUMBER PLATE LAMP L/R <i>neu</i>	2	45.00	+	90.00
REAR TAILGATE OUTER HANDLE (BLACK) <i>could</i>	1	133.40	✓	133.40
REAR TAILGATE REFLECTOR L/R <i>neu</i>	2	125.00	+	250.00
REAR TAILGATE WEATHER STRIP <i>cut</i>	1	92.30	✓	92.30
REAR TAILGATE WINDSCREEN MOULDING <i>neu</i>	1	224.70	✓	224.70
REAR TAILGATE WIPER ARM <i>cut</i>	1	68.20	✓	68.20
REAR TAILGATE WIPER ARM COVER <i>could</i>	1	30.00	✓	30.00
REAR TAILGATE WIPER MOTOR <i>Daugd</i>	1	268.00	✓	268.00
REAR TAILLAMP L/R <i>could</i>	2	268.90	✓	537.80
REAR TAILLAMP PANEL L/R <i>Reps</i>	2	108.90	+	217.80

Subtotal before discount

6,451.40

Percentage discount 20%

1,290.28

Sub-total 1

5,161.12

REAR BUMPER CLIPS - SET <i>neu</i>	1	50.00	30	50.00
REAR BUMPER REVERSE SENSOR <i>Daugd</i>	1	280.00	20	280.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET <i>neu</i>	1	50.00	10	50.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

ZHENG SHIXI
BLK 613 BUKIT PANJANG RING ROAD
#19-852
SINGAPORE 670613

Contact : 91378759

TAX INVOICE

Repair Code : CLM17280

Date in : 05/07/2022

Vehicle Num. : SMS1969U

Model : HONDA FIT 1.3GF CVT

Chassis/Eng# : GK31354510/L13B1465439

REAR FENDER INNER TRIM BOARD CLIPS L/R - SET <i>Nlu</i>	2	50.00	<i>30</i>	100.00
REAR FLOOR PANEL INSULATOR MAT <i>Nlu</i>	1	300.00	<i>+</i>	300.00
REAR TAILGATE CAMERA <i>2nd</i>	1	800.00	<i>380</i>	800.00
REAR TAILGATE INNER TRIM BOARD CLIPS - SET <i>Nlu</i>	1	50.00	<i>30</i>	50.00
REAR TAILGATE NUMBER PLATE <i>3rd</i>	1	25.00	<i>+</i>	25.00
REAR TAILGATE NUMBER PLATE HOLDER <i>800</i>	1	50.00	<i>+</i>	50.00
REAR TAILGATE OUTER HANDLE CLIPS - SET <i>on</i>	1	40.00	<i>20</i>	40.00
REAR TAILGATE WINDSCREEN SEALANT <i>Nlu</i>	1	80.00	<i>60</i>	80.00
REAR TAILLAMP CLIPS L/R - SET <i>Nlu</i>	2	30.00	<i>40</i>	60.00
Subtotal before discount				1,885.00
Percentage discount 0%				0.00
Sub-total 2				1,885.00
Parts-total				7,046.12

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.

✓ 80.00

To remove, reinstall tailgate windscreen

120 ~~150.00~~

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

60 ~~100.00~~

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

800 ~~1,200.00~~

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

800 ~~1,000.00~~

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

ZHENG SHIXI
BLK 613 BUKIT PANJANG RING ROAD
#19-852
SINGAPORE 670613

Contact : 91378759

TAX INVOICE

Repair Code : CLM17280
Date in : 05/07/2022
Vehicle Num. : SMS1969U
Model : HONDA FIT 1.3GF CVT
Chassis/Eng# : GK31354510/L13B1465439

To apply anti-rust chemical on repaired and replaced panel.

To transfer rear tailgate inner trim board, wiper motor, mechanism lock outer handle.

1980	60	120.00
	60	80.00
Labour Total		2,730.00
Parts & Labour Total		9,776.12

*** This is a computer-generated document which requires no signature.***

page 4

Adrian L
4/5 07/07/22

06 days.

total: 6428

4/5: 5.11C ✓

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: