

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.  
79 Robinson Road #09-01  
Singapore 068897

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Sharon Lim

Date: 08 Jul 2022

## **Preliminary Advice**

Vehicle No	: SLD3980M	Accident Date	: 13/06/2022
Make	: HONDA VEZEL	Policy No.	: SPMF1000000542
Assignment Date	: 07/07/2022	Excess	: S\$2,000.00
Date of Inspection	: 8/7/2022	Est. Duration of Repair	: 15
Inspection At	: DING AUTO PTE LTD		

### **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	35,077.80
Revised Amount	:S\$	19,076.50
Check Items (Estimated)	:S\$	5,129.50
Total	:S\$	24,206.00
Lump Sum Repair	:S\$	

### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	57,000.00
COE / PARF Rebate	:S\$	25,152.00
Salvage Value	:S\$	
Margin for Repair	:S\$	31,848.00

### **Remarks**

( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

( X ) Other comments : Lump Sum Repair

Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost .

At the time of inspection, all the tyres of the insured vehicle were found to be in serviceable condition with remaining tread depth of approximately 2mm.