

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 07 Jul 2022)
 Parts: 144 HONDA VEZEL 1.5 CVT ABS D/AIRBAG 2WD SDR (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Ding Auto Pte Ltd/SLD3980M/07/07/2022 16:15
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER	0.00	0.00	M/I *220.00 F
2	1		*FRONT BUMPER RETAINER RH	0.00	0.00	CM *15.00 F
3	1		*FRONT BUMPER RETAINER LH	0.00	0.00	CM *15.00 F
4	1		*FRONT BUMPER REINFORCEMENT ✓	0.00	0.00	Ag *240.00 F
5	1		*FRONT BUMPER LOWER GARNISH	0.00	0.00	M/I *145.00 F
6	1		*FRONT SUPPORT PANEL	0.00	0.00	Ag *400.00 F
7	1		*FRONT SUPPORT PANEL UPPER GARNISH	0.00	0.00	M/I *45.00 F
8	1		*FRONT GRILLE BASE	0.00	0.00	M/I *220.00 F
9	1		*FRONT GRILLE CHROME PANEL	0.00	0.00	M/I *180.00 F
10	1		*FRONT GRILLE BADGE	0.00	0.00	M/I *35.00 F
11	1		*FRONT GRILLE CENTRE BRACKET	0.00	0.00	M/I *25.00 F
12	1		*FRONT LOWER GRILLE	0.00	0.00	M/I *70.00 F
13	1		*BONNET ✓	0.00	0.00	R *480.00 F X
14	1		*BONNET HINGE RH ✓	0.00	0.00	R *35.00 F X
15	1		*BONNET HINGE LH ✓	0.00	0.00	R *35.00 F X
16	1		*BONNET INSULATION	0.00	0.00	Rn *85.00 F X
17	1		*BONNET STAY	0.00	0.00	Rn *40.00 F X
18	1		*BONNET LOCK	0.00	0.00	R *75.00 F X
19	1		*BONNET FRONT SEAL	0.00	0.00	Rn *25.00 F X
20	1		*BONNET STOPPER	0.00	0.00	Rn *40.00 F X
21	1		*FRONT FENDER RH	0.00	0.00	Rn *230.00 F
22	1		*FRONT FENDER LH	0.00	0.00	R *230.00 F X
23	1		*FRONT FENDER ARCH MOULDING RH	0.00	0.00	M/I *60.00 F
24	1		*FRONT FENDER ARCH MOULDING LH	0.00	0.00	M/I *60.00 F
25	1		*FENDER WHEEL COVER RH	0.00	0.00	M/I *85.00 F
26	1		*FENDER WHEEL COVER LH	0.00	0.00	M/I *85.00 F
27	1		*HEADLAMP ASSY RH	M/I CM 0.00	0.00	*1,100.00 F
28	1		*HEADLAMP ASSY LH	Rn 0.00	0.00	*1,100.00 F X
29	1		*HEADLAMP BRACKET RH	0.00	0.00	CM *25.00 F
30	1		*HEADLAMP BRACKET LH	0.00	0.00	CM *25.00 F
31	1		*FOG LAMP ASSY RH	0.00	0.00	M/I *160.00 F
32	1		*FOG LAMP ASSY LH	0.00	0.00	M/I *160.00 F
33	1		*FOG LAMP COVER RH	0.00	0.00	M/I *30.00 F
34	1		*FOG LAMP COVER LH	0.00	0.00	M/I *30.00 F
35	1		*RADIATOR ASSY	M/I Rn 0.00	0.00	*670.00 F
36	1		*RADIATOR UPPER BRACKET RH	0.00	0.00	R *15.00 F X
37	1		*RADIATOR UPPER BRACKET LH	0.00	0.00	R *15.00 F X
38	1		*CONDENSOR ASSY	T/I Rn 0.00	0.00	*450.00 F
39	1		*AIR-COND SUCTION HOSE	0.00	0.00	Rn *135.00 F
40	1		*AIR-COND DISCHARGE HOSE ✓	0.00	0.00	Rn *105.00 F
41	1		*FAN COVER ✓	CM 0.00	0.00	*85.00 F
42	1		*FAN MOTOR (X 2PCS) ✓	Rn 0.00	0.00	*220.00 F X
43	1		*FAN BLADE (X 2PCS) ✓	CM 0.00	0.00	*50.00 F
44	1		*ENGINE MOUNTING RH ✓	0.00	0.00	Rn *135.00 F X
45	1		*ENGINE MOUNTING LH ✓	0.00	0.00	Rn *185.00 F X
46	1		*ENGINE LOWER MOUNTING ✓	0.00	0.00	Rn *65.00 F X
47	1		*ENGINE AIR INTAKE MANIFOLD ASSY	0.00	0.00	Rn *390.00 F X

franchise part.

26,998.00

2,699.80

29,697.80

Generated using Merimen e-Claims IEAS

Miscellaneous Items

1	1	AIRBAG ECU - REPROGRAMMING	450.00
2	1	BUMPER, WHEEL COVER, PANEL GARNISH & SEAL CLIPS	150.00
Sub Total (S\$)			600.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

BODY REPAIR, PANEL BEATING & ALIGN - ACCIDENT AREA	New	2,000.00
SPRAY PAINT - FRONT BUMPER, BONNET, FRONT FENDERS (X2), FRONT DOORS (X2) & SUPPORT PANEL	New	1,800.00
REMOVE & REFIT UNDERCARRIAGE COMPONENTS	New	350.00
REMOVE & REFIT ENGINE COMPONENTS	New	350.00
ALIGN HEADLAMP/FOG LAMP & TEST WIRING	New	120.00
REFILL AIR-COND GAS	New	80.00
REFILL RADIATOR COOLANT	New	80.00

Gross Labour Cost (S\$) 4,780.00

Ding Auto Pte Ltd/SLD3980M/07/07/2022 16:15. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

