

HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 07.07.2022

TO : AXA MOTOR CLAIMS DEPTS
VEHICLE NO : YQ6773C
MODEL : TOYOTA DYNA
DATE OF ACCIDENT : 07.07.2022
TIME OF ACCIDENT : 09:30 HRS

JHHA GV4680K002219.

Xiao Tong

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT CHASSIS CROSS MEMBER <i>new</i>	1	\$ 2,752.60	\$ 2,752.60
2	FRONT BUMPER <i>Distorted</i>	1	\$ 748.90	\$ 748.90
3	FRONT BUMPER BRACKET RH <i>Bent</i>	1	\$ 312.70	\$ 312.70
4	HEAD LAMP LH <i>RH. Cncl'd</i>	1	\$ 1,080.10	\$ 1,080.10
5	HEAD LAMP LOWER RUBBER <i>new</i>	1	\$ 47.20	\$ 47.20
6	FRONT FOGLAMP COVER RH <i>Distorted</i>	1	\$ 75.20	\$ 75.20
7	FRONT GRILLE <i>Cncl'd</i>	1	\$ 598.60	\$ 598.60
8	FRONT GRILLE LOGO <i>new</i>	1	\$ 90.20	\$ 90.20
9	FRONT PANEL <i>Distorted</i>	1	\$ 1,291.80	\$ 1,291.80
10	FRONT PANEL EMBLEM 'DYNA' <i>new</i>	1	\$ 78.60	\$ 78.60
11	FRONT WIPER PANEL <i>Rejs</i>	1	\$ 349.60	\$ 349.60
12	FRONT STEERING BOX <i>new</i>	1	\$ 1,198.10	\$ 1,198.10
13	FRONT DOOR STEP PANEL GARNISH RH <i>cut</i>	1	\$ 327.10	\$ 327.10
14	FRONT WINDSCREEN RUBBER <i>new</i>	1	\$ 399.40	\$ 399.40
15	FRONT CORNER PANEL RH <i>Rejs</i>	1	\$ 364.20	\$ 364.20
16	REAR CHASSIS CROSS MEMBER <i>Rejs</i>	1	\$ 789.50	\$ 789.50
17	TAILGATE <i>Distorted</i>	1	\$ 1,370.00	\$ 1,370.00
18	TAILGATE HINGE <i>2 pieces Bent</i>	4	\$ 165.00	\$ 660.00
19	TAILGATE SIDE LOCK <i>new RH Bent</i>	2	\$ 125.00	\$ 250.00
20	TAILGATE STOPPER RUBBER <i>RH Bent Missing</i>	2	\$ 35.90	\$ 71.80
21	TAILGATE STOPPER BRACKET <i>RH Bent</i>	2	\$ 175.00	\$ 350.00
22	TAILGATE STICKER 'TOYOTA' <i>new</i>	1	\$ 167.60	\$ 167.60
23	CARGO BED SIDE PANEL RH <i>Rejs</i>	1	\$ 1,522.10	\$ 1,522.10
24	SIDE GATE SAFETY LOCK <i>RH Bent New</i>	2	\$ 132.10	\$ 264.20
25	TAIL LAMP <i>RH Cncl'd</i>	2	\$ 251.80	\$ 503.60

330 180
125
35.90
175
1322.10
251.30

TO : AXA MOTOR CLAIMS DEPTS
 VEHICLE NO : YQ6773C
 MODEL : TOYOTA DYNA
 DATE OF ACCIDENT : 07.07.2022
 TIME OF ACCIDENT : 09:30 HRS

26	TAIL LAMP SUPPORT BRACKET <i>RH Bent</i>	2	\$ 185.00	\$ 370.00	<i>185</i>
27	TAIL LAMP REFLECTOR (ROUND) RH <i>crackd</i>	1	\$ 65.10	\$ 65.10	<i>✓</i>
28	TAIL LAMP BACK COVER GARNISH RH <i>dkd</i>	1	\$ 26.80	\$ 26.80	<i>✓</i>
29	REAR NUMBER PLATE LAMP <i>new</i>	2	\$ 69.10	\$ 138.20	<i>+</i>
30	REAR STICKER 'DYNA' <i>new</i>	1	\$ 85.70	\$ 85.70	<i>✓</i>
31	REAR EXHAUST PIPE <i>Bent</i>	1	\$ 681.50	\$ 681.50	<i>✓</i>
32	REAR EXHAUST BRACKET <i>Bent</i>	1	\$ 78.90	\$ 78.90	<i>✓</i>
33	REAR EXHAUST BRACKET MOUNTING <i>end</i>	1	\$ 48.20	\$ 48.20	<i>✓</i>
34	REAR EXHAUST BRACKET BOLT <i>Broken</i>	1	\$ 39.80	\$ 39.80	<i>✓</i>
35	CENTER EXHAUST PIPE <i>Bent</i>	1	\$ 3,540.80	\$ 3,540.80	<i>local Pnt 300.00 (SW)</i>
36	CENTER EXHAUST PIPE BRACKET <i>Bent</i>	1	\$ 78.60	\$ 78.60	<i>✓</i>
37	CENTER EXHAUST PIPE MOUNTING <i>toe</i>	1	\$ 48.20	\$ 48.20	<i>✓</i>
38	CENTER EXHAUST BOX <i>new</i>	1	\$ 818.70	\$ 818.70	<i>X</i>
39	CENTER EXHAUST BOX MOUNTING <i>new</i>	3	\$ 45.80	\$ 137.40	<i>+</i>
40	REAR WHEEL BACK FENDER RH <i>Bent Pnt</i>	1	\$ 248.60	\$ 248.60	<i>+</i>
41	REAR WHEEL BACK FENDER BRACKET RH <i>Bent</i>	1	\$ 125.70	\$ 125.70	<i>✓</i>
42	REAR WHEEL BACK FENDER MUDFLAP RH <i>dkd</i>	1	\$ 125.10	\$ 125.10	<i>✓</i>
43	REAR END PANEL <i>Dented</i>	1	\$ 1,245.00	\$ 1,245.00	<i>495</i>
44	REAR SPARE TYRE CHAIN BOX <i>Damaged</i>	1	\$ 265.70	\$ 265.70	<i>✓</i>

S.N: 400 965670.
 724252

TOTAL PRICE \$ 23,831.10
 LESS 25% \$ 5,957.78
SUB TOTAL PRICE \$ 17,873.33

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT NUMBER PLATE <i>Missing</i>	1	\$ 50.00	\$ 50.00
2	FRONT GRILLE CLIP (SET) <i>new</i>	1	\$ 40.00	\$ 40.00
3	FRONT PANEL SEALANT <i>new</i>	1	\$ 150.00	\$ 150.00
4	DASHBOARD CLIP (SET) <i>3 x 150</i>	1	\$ 150.00	\$ 150.00
5	DASHBOARD CENTER GARNISH CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
6	FRONT WINDSCREEN GLASS SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00
7	FRONT DOOR LTA STICKER RH <i>new</i>	1	\$ 80.00	\$ 80.00
8	POWER STEERING OIL <i>new</i>	1	\$ 120.00	\$ 120.00
9	REAR NUMBER PLATE <i>Bent</i>	1	\$ 50.00	\$ 50.00
10	TAIL GATE '70KM/H' STICKER <i>new</i>	1	\$ 40.00	\$ 40.00
11	REAR SPARE TYRE (BIG) <i>3 x 150 cut</i>	1	\$ 480.00	\$ 480.00
12	REAR SPARE TYRE (SMALL) <i>new</i>	1	\$ 250.00	\$ 250.00
45	REAR REINFORCEMENT <i>Bent</i>	1	\$ 2,200.00	\$ 2,200.00
13	REAR TYRE RH <i>new cut</i>	1	\$ 380.00	\$ 380.00
14	REAR END PENEL SEALANT <i>new</i>	1	\$ 150.00	\$ 150.00

TO : AXA MOTOR CLAIMS DEPTS
 VEHICLE NO : YQ6773C
 MODEL : TOYOTA DYNA
 DATE OF ACCIDENT : 07.07.2022
 TIME OF ACCIDENT : 09:30 HRS

15	REVERSE SENSOR (SET) <i>Damaged</i>	1	\$ 220.00	\$ 220.00 <i>200.</i>
----	-------------------------------------	---	-----------	----------------------------------

1855

TOTAL \$ 4,490.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, WELD ,CUT, ADJUST, KNOCK	\$ 2,000.00	<i>800.</i>
2	TO PUTTY, SPRAY PAINT, POLISH WAX	\$ 1,400.00	<i>900.</i>
3	TO SPRAY TUFF COAT	\$ 250.00	<i>60</i>
4	WIRING, BULB CHECKING	\$ 80.00	<i>30</i>
5	CONDUCT WATER TER LEAKAGE TEST	\$ 80.00	<i>x</i>
6	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	\$ 250.00	<i>x.</i>
7	REFOCUS HEADLAMP BEAM	\$ 60.00	<i>x</i>
8	REMOVE AND REFIX AIRCON BLOWER,COOLING COIL,AIR CON CONDENSER AND REFILL AIRCON GAS	\$ 250.00	<i>x</i>
9	REMOVE AND REINSTALL DASHBOARD	\$ 650.00	<i>x</i>
10	REMOVE AND REFIX FRONT WINDSCREEN	\$ 120.00	<i>✓</i>
11	REMOVE AND REFIX FRONT VIDEO RECORDER	\$ 80.00	<i>x.</i>
12	RESET RADIO SYSTEM	\$ 200.00	<i>x</i>
13	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	<i>x</i>

1510

TO : AXA MOTOR CLAIMS DEPTS
VEHICLE NO : YQ6773C
MODEL : TOYOTA DYNA
DATE OF ACCIDENT : 07.07.2022
TIME OF ACCIDENT : 09:30 HRS

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, WELD ,CUT, ADJUST, KNOCK	\$ 2,200.00	900.
2	TO PUTTY, SPRAY PAINT, POLISH WAX	\$ 1,600.00	800.
3	REMOVE AND REFIX REAR RAILING	\$ 350.00	x.
4	To remove rear and centre exhaust Pipe	300	160.
5	REMOVE AND REFIX REVERSE SENSOR	\$ 80.00	50.
6	REMOVE AND REFIX REAR FLOOR ALUMINIUM	\$ 650.00	x
7	REAR CHASSIS ALIGNMENT	\$ 250.00	200

TOTAL \$ 10,730.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 22,363.33
TOTAL LABOUR COST : \$ 10,730.00
TOTAL REPAIR COST : \$ 33,093.33

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP : 8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian L
h/s 08/07/22.

12 days

total: 13817.52

h/s: 10.8K.

10.8K