

ZWR 800395888

ESTIMATE OF REPAIR

Veh# : SNA4968K

Accident Date : 6/7/2022

Location : 11 UNITY STREET CARPARK

TPA IG
Xiao Tony

Model:

TOYOTA NOAH

13/8/2019

3P:

SLX9810B (AIG)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Front bumper <i>Re-boned</i>	2,238.60	1025	-
2	10 pcs	Front bumper clips <i>Neu</i>	-	50.00	30
3	2 pcs	Front bumper o/s & n/s chrome <i>Neu</i>	420.00	x	-
4	2 pcs	Front bumper o/s & n/s retainer <i>Neu</i>	293.00	x	-
5	2 pcs	Front o/s & n/s head-lamp (HID) <i>Neu</i>	9,277.80	x	-
6	2 pcs	Front o/s & n/s head-lamp chrome <i>Neu</i>	396.20	+	-
7	1 pc	Front grille <i>Re-boned</i>	2,680.50	645	-
8	12 pcs	Front grille clips <i>Neu</i>	-	60.00	20
9	1 pc	Front grille emblem <i>Neu</i>	145.00	68	-
10	1 pc	Front enforcement <i>Neu</i>	520.00	x	-
11	1 pc	Front enforcement sponge <i>Neu</i>	168.40	x	-
1738 S/N 50 Sub-Total:			16,139.50	110.00	0.00
			25%	0%	10%
1303.50 After Less %:			12,104.63	110.00	0.00
Labour					
1		To dismantle damaged parts, straighten & welding.	800.00	200	
2		To spray painting.	600.00	250	
3		To wrap front grille	150.00	120	
4		To remove & refit front camera	50.00	✓	
5		To re-set electrical system.	250.00	x	
6		To check wiring.	50.00	30	
Sub-Total:			1,900.00		
Total:			14,114.63		
After Less 20%:			11,291.70		

Chan

Chan San Choon
Director
DipEng, AAE MIMI,MSAE(Aust)



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian C
1/8 26/07/22
03 days

Mobil 1



PAYNOW

total: 2003.50
1/8: 1.6K