

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG22006514/ACE2**Date:** 09/11/2022**REFERENCE**

Insured/Claimant:	LIM SIM THONG	Policy No:	7220020330	
Date of Loss:	03/07/2022	Nature of Claim:	OD	Claim No: 3453904790SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SNE2372X</b>	Engine No:	DEM033886
Make & Model:	AUDI A4, 2.0 TFSI S-TRONIC (A)	Chassis No:	WAUZZZF4XMA084028
Reg. Date:	25/02/2022 (Man. Year: 2021)	Odometer:	9740 km
Colour:	White		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$215,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,508.00	1,069.04	1,438.96	57.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,772.00	1,742.00	3,030.00	63.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>7,280.00</b>	<b>2,811.04</b>	<b>4,468.96</b>	<b>61.39</b>
<b>- Excess (S\$)</b>	<b>1,100.00</b>	<b>1,100.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>6,180.00</b>	<b>1,711.04</b>	<b>4,468.96</b>	<b>72.31</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>432.60</b>	<b>119.77</b>	<b>312.83</b>	<b>72.31</b>
<b>Nett Amount (S\$)</b>	<b>6,612.60</b>	<b>1,830.81</b>	<b>4,781.79</b>	<b>72.31</b>

**INSPECTION**

Date of Assignment:	08/07/2022	
Date Inspected:	07/07/2022	Inspected At: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	3.0 days	

**Adjuster:** ADRIAN LING**Manager:** CELINE FONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER - RH	Dented	1,227.00 FS	*981.60 FS
2	1		*FRONT FENDER ATTACHMENT PARTS - RH	Not Necessary	211.00 FS	*- FS
3	1		*FRONT FENDER CLOSING ELEMENT - RH	Not Necessary	81.00 FS	*- FS
4	1		*FRONT FENDER BRACKET - RH	Not Necessary	41.00 FS	*- FS
5	7		*FRONT FENDER RIVET - RH	Necessary	27.00 FS	*21.28 FS
6	1		*FRONT FENDER DEFORMATION BRACKET - RH	Not Necessary	55.00 FS	*- FS
7	1		*FRONT FENDER BRACKET - RH	Not Necessary	36.00 FS	*- FS
8	1		*FRONT FENDER BRACE - RH	Not Necessary	132.00 FS	*- FS
9	1		*FRONT WHEEL HOUSING LINER - RH	Not Necessary	262.00 FS	*- FS
10	1		*FRONT WHEEL SPOILER - RH	Not Necessary	52.00 FS	*- FS
11	1		*FRONT FENDER FLEDGE COVER - RH LONG	Cracked	35.00 FS	*27.52 FS
12	1		*FRONT FENDER FLEDGE COVER - RH SHORT	Cracked	49.00 FS	*38.64 FS
13	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS
					<b>Total Parts (\$\$)</b>	<b>2,508.00      1,069.04</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	0.00
2	TO DISMANTLE AND REINSTALL FRONT BUMPER. TO RENEW RHS FRONT FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS . REINSTALL ALL PARTS REMOVED	New	2,100.00	1,000.00
3	TO RESPRAY RHS FRONT FENDER AND BONNET	New	2,000.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (S\$)</b>			<b>4,772.00</b>	<b>1,742.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >