



AUTOBACS CAR CARE (SINGAPORE) PTE. LTD.

8 Kaki Bukit Ave 4 #08-40/45/46 Premier@Kaki Bukit S(415875)

Tel : 6702 1555 Fax : 6702 1444

Co. Reg No. : 201500047H GST No. : 201500047H

TO	: INDIA (SMH738J)	DATE	: 6-Jul-22
ATTENTION	: MOTOR CLAIMS DEPARTMENT	JOB TYPE	: T/P CLAIMS
OWNER PARTICULAR			
OWNER ID	: SXXXX449Z	P -	
		S -	
		L -	
VEHICLE DETAILS			
VEHICLE NO.	: SKC292C	SUB TOTAL :	
MODEL / MAKE	: LEXUS ES300H		
CHASSIS NO.	: JTHB21B1402119655		
ACCIDENT DETAIL			
DATE	: 6-Jul-22		
TIME	: 10:25HRS	CONTACT PERSON	: MR. WINSON 91866680

QUOTATION SUMMARY

PAGE 01

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	rear door Rh <i>Dehid</i>	1	\$ 1,271.42	\$ ✓ 1,271.42
2	rear door black tape top Rh	1	\$ 65.65	\$ ✓ 65.65
3	rear door black tape front Rh	1	\$ 61.39	\$ ✓ 61.39
4	rear door black tape back Rh	1	\$ 48.25	\$ ✓ 48.25
5	rear door sticker Rh	1	\$ 42.59	\$ ✓ 42.59
6	rear door hybrid emblem Rh <i>New</i>	1	\$ 91.55	\$ ✓ 91.55
7	rear fender Rh <i>Repair</i>	1	\$ 1,683.00	\$ + 1,683.00
8	rear fender sticker Rh <i>New</i>	1	\$ 58.31	\$ ✓ 58.31
9	rear fender inner shield Rh <i>Dehid</i>	1	\$ 223.67	\$ ✓ 223.67
10	rear fender inner panel Rh <i>Repair</i>	1	\$ 454.00	\$ + 454.00
11	rear bumper <i>Dehid</i>	1	\$ 1,249.45	\$ ✓ 1,249.45
12	rear bumper side retainer Rh <i>New</i>	1	\$ 188.00	\$ + 188.00
13	rear bumper lower diffuser with chrome <i>New</i>	1	\$ 677.00	\$ + 677.00
14	rocker side skirting Rh <i>Dehid</i>	1	\$ 730.75	\$ ✓ 730.75
15	rear 18" sport rim Rh (original) <i>cat</i>	1	\$ 2,941.96	\$ ✓ 2,941.96
16	rear knuckle arm Rh <i>3M</i>	1	\$ 639.51	\$ + 639.51
17	rear knuckle arm bearing Rh <i>3M</i>	1	\$ 629.87	\$ + 629.87
			TOTAL PRICE	\$ 11,056.37
			LESS -10%	\$ (1,105.64)
			SUB TOTAL PRICE	\$ 9,950.73

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	rear fender inner shield clips set Rh <i>New</i>	1	\$ 60.00	\$ 60.00 30
2	rear bumper clips set <i>New</i>	1	\$ 80.00	\$ 80.00 30
3	rocker side skirting clips set Rh <i>New</i>	1	\$ 60.00	\$ 60.00 30
4	rear 18" tyre Rh <i>New</i>	1	\$ 480.00	\$ 480.00 +
			TOTAL	\$ 680.00

QUOTATION SUMMARY

PAGE 02

CLAIMS DETAIL : LABOUR CHARGES AND SPRAY PAINTING

TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	\$ 1,320.00	650.	
TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	\$ 1,320.00	800	
TO APPLY ANTI-RUST & TUFF KOTE	\$ 95.00	60.	
TO PERFORM LIGHTING & WIRING CHECK	\$ 80.00	30	
TO DISMANTLE & REINSTALL REAR WINDSCREEN PERFORM	\$ 150.00	x	
TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR WITH DISTANCE SETTING	\$ 120.00	60.	
TO DISMANTLE & REPLACED REAR UNDER CARRIAGE COMPONENT RH TO PERFORM FACILITATE REPAIRS	\$ 280.00	x	
TO SEND VEHICLE FOR 3D COMPUTERISED TO PERFORM CHECK & ADJUSTED ALL WHEEL ALIGNMENT	\$ 100.00	80	
TO PERFORM DIAGNOSTIC CHECK & RESET MEMORY FAULT CODE TO IDENTIFICATION STANDARD	\$ 380.00	180.	
TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR	\$ 250.00	80.	

TOTAL \$ 4,095.00

1940

Admin Lj
P/P 07/07/22
06 Pays

ESTIMATE REPORT

TOTAL PARTS COST : \$ 10,630.73
TOTAL LABOUR COST : \$ 4,095.00
TOTAL REPAIR COST : \$ 14,725.73

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total: 8136.49
(P/P)