

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Allianz Insurance Singapore Pte.
Ltd.
79 Robinson Road #09-01
Singapore 068897

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: JANICE KOH

Date: 12 Jul 2022

Preliminary Advice

Vehicle No	: SMQ3761Z	Accident Date	: 24/06/2022
Make	: MERCEDES-BENZ E200	Policy No.	: SP2000698649
Assignment Date	: 07/07/2022	Excess	: S\$2,000.00
Date of Inspection	: 08/07/2022	Est. Duration of Repair	: 7
Inspection At	: AUTO INSURE PTE LTD (HQ) (WOODLANDS) 6 MARSILING LANE SINGAPORE 739145		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$ 36,168.50
Revised Amount	:S\$ 12,848.00
Check Items (Estimated)	:S\$ 3,899.50
Total	:S\$ 16,747.50

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$ 150,000.00
COE / PARF Rebate	:S\$ 58,657.00
Salvage Value	:S\$

Margin for Repair

:S\$ 91,343.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.