



Auto Insure Pte. Ltd.
6 Marsiling Lane
Singapore (739145)
E: claims01@autoinsure.com.sg
W: www.autoinsure.com.sg
T: 3157 2626 F: 6368 0081
GST No.: 201437380M

Page No.1

AUTOMOBILE ASSESSMENT REPORT

Our Ref: **SMQ3761Z (MARVYN)**

Date: **27-Jun-22**

BY EMAIL ONLY
(claims01@autoinsure.com.sg)

ATTENTION: MOTOR CLAIMS DEPT

Allianz Insurance Singapore Pte. Ltd

79 Robinson Road
#09-01,
Singapore 068897

Assessed Vehicle No : SMQ3761Z
Car Make and Model : MERCEDES BENZ A200 COMPT SALN PROGRESSIVE (R18 LED)
Date of Accident : 24-Jun-22
Date of Assessment : 27-Jun-22

We have carried out a physical assessment of SMQ3761Z at our workshop Auto Insure Pte Ltd sustained damages to the FRONT & LF SIDE portion of the vehicle.


4. DESCRIPTION OF DAMAGE

At the time of the inspection observed that this vehicle had sustained damages to the FRONT & LEFT HAND SIDE portion of the vehicle.

Please see attached schedule for details.

Remarks: NIL

Estimated Amount : **P/P**
Adjusted Amount : **\$ 36,153.70**
Est. Repair Days : **18**



Pursuant to your instruction, we have **AUTHORIZED to** repair.
The assessment was conducted on a "**WITHOUT PREJUDICE**" basis.

If we are not notified of anything within 14 Days from the date hereof, this report shall be treated as correct.

Disclaimer

This report is intended for the exclusive use of the addressee solely in relation to the loss of occurrence in which the assessed vehicle is involved.

No liability or responsibility whatsoever shall be held by
AUTO INSURE PTE. LTD. For any reliance on this report by any third party.

Our Ref: **SMQ3761Z**

S/NO	QTY	DESCRIPTIONS	ASSESSED CONDITION	EST. BY WORKSHOP
PARTS REPLACEMENT - LIST ITEMS				
1	1	BONNET ?		\$ 1,320.00
2	1	BONNET HINGE RH = 50T		\$ 110.00
3	1	BONNET HINGE LH = 50T		\$ 110.00
4	1	BONNET LOCK ?		\$ 200.00
5	1	FRONT BUMPER - ee		\$ 1,010.00
6	1	FRONT GRILLE ?		\$ 640.00
7	1	FRONT GRILLE MOULDING TOP ?		\$ 205.00
8	1	FRONT GRILLE MOULDING LH x NN		\$ 60.00
9	1	FRONT GRILLE MOULDING RH - Cut		\$ 60.00
10	1	FRONT GRILLE LOGO (MERCEDES) ?		\$ 175.00
11	1	FRONT BUMPER LOWER GRILLE - ee		\$ 120.00
12	1	FRONT BUMPER SIDE RETAINER RH - Cut		\$ 90.00
13	1	FRONT BUMPER SIDE RETAINER LH x		\$ 90.00
14	1	FRONT BUMPER LOWER COVER RH - B's		\$ 50.00
15	1	FRONT BUMPER LOWER COVER LH x NN		\$ 50.00
16	1	FRONT BUMPER LOWER COVER ?		\$ 260.00
17	1	FRONT BUMPER PARKING SENSORS INNER LH x		\$ 165.00
18	1	FRONT BUMPER PARKING SENSORS CENTER LH x		\$ 165.00
19	1	FRONT BUMPER PARKING SENSORS INNER RH ?		\$ 165.00
20	1	FRONT BUMPER PARKING SENSORS CENTER RH x		\$ 165.00
21	1	FRONT HEAD LAMP RH x NN		\$ 2,305.00
22	1	FRONT HEAD LAMP LH - o/a		\$ 2,305.00
23	1	FRONT SUPPORT PANEL ?		\$ 280.00
24	1	FRONT FENDER RH - Bnc		\$ 540.00
25	1	FRONT FENDER LH x Repair		\$ 540.00
26	1	FRONT DOOR LH x Repair Bnc		\$ 1,395.00
27	1	SIDE MIRROR HOUSING LH x		\$ 540.00
28	1	SIDE MIRROR COVER LH x		\$ 200.00
29	1	SIDE MIRROR GLASS LH x		\$ 140.00
30	1	FRONT DOOR HINGE UPPER LH x NN		\$ 105.00
31	1	FRONT DOOR HINGE LOWER LH x		\$ 105.00
32	1	FRONT DOOR HANDLE LH x		\$ 475.00
33	1	FRONT DOOR HANDLE CAP LH x		\$ 110.00
34	1	FRONT DOOR LOCK LH x		\$ 265.00
35	1	REAR DOOR LH - Bnc		\$ 1,850.00
36	1	REAR DOOR HINGE UPPER LH x		\$ 105.00
37	1	REAR DOOR HINGE LOWER LH x		\$ 105.00
38	1	REAR DOOR LOCK LH x		\$ 265.00
39	1	REAR DOOR HANDLE LH x		\$ 475.00
40	1	B PILLAR LH x		\$ 2,700.00
41	1	SIDE PANEL LH - TN		W/B PILLAR
42	1	REAR FENDER LH x Repair		\$ 2,700.00
43	1	REAR BUMPER x Repair		\$ 1,080.00

44	1	FRONT DOOR RH X <i>repair</i>	\$	1,980.00
45	1	ENGINE OIL SUMP ?	\$	300.00
46	1	FRONT WHEEL RIM LH <i>cut</i>	\$	1,020.00
47	1	REAR WHEEL RIM LH	\$	1,020.00
48	1	FRONT WHEEL RIM RH X <i>NN</i>	\$	1,020.00
			SUB TOTAL	\$ 28,935.00
			MARGIN 10%	\$ 2,893.50
			TOTAL AMOUNT	\$ 31,828.50

Our Ref: **SMQ3761Z**

S/NO	QTY	SPECIAL NETT ITEMS	ASSESSED CONDITION	EST. BY WORKSHOP
1	1	FRONT BUMPER CLIPS		\$ 50.00
2	1	FRONT FENDER INNER SHIELD CLIPS RH	<i>Sub</i>	\$ 35.00
3	1	FRONT FENDER INNER SHIELD CLIPS LH	<i>Sub</i>	\$ 35.00
4	1	FRONT WHEEL TYRE RH X		\$ 380.00
5	1	FRONT WHEEL TYRE LH X <i>NN</i>		\$ 380.00
			SUB TOTAL	\$ 500.00
			TOTAL PARTS COST	\$ 32,328.50

880

Supplementary.

ENGINE oil / MC.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Part prices are subject to confirmation
- Third party claims on "Without Prejudice" basis
- No illegal modifications allowed
- Supplemental charges may be conveyed and is subject to the relevant Insurance Company

Acknowledged by Repairer:
Signature:
Date:

Our Ref: **SMQ3761Z**

S/NO	DESCRIPTION	EST. BY WORKSHOP
LABOUR & PAINTWORK		
1	REMOVE, REFIT AND REPAIR AFFECTED DAMAGED PARTS	\$ 1,800.00
2	TO CONDUCT ANALIGNMENT AND WHEEL BALANCING	\$ 200.00
3	SIMPLE WIRING	\$ 20.00
4	ANTI RUST COATING	\$ 20.00
5	PAINT MATERIALS PER PANEL	\$ 1,400.00
6	SUNDRIES	\$ 20.00
TOTAL BEFORE GST		\$ 35,788.50
LESS EXCESS		\$ 2,000.00
TOTAL BEFORE GST		\$ 33,788.50
7% GST		\$ 2,365.20
TOTAL REPAIR COST		\$ 36,153.70

800
60
/
/
/
X NN
36168.50

Adjustments / Recommendations

Our estimator have throughly inspected each and every item on the estimate against physical damage found on the vehicle and have listed the breakdown of our finding and recommendation.

****This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.**

***On a separate note, please let us have your authorize repair confirmation and/or approval for the above OD case in your next reply.

Yours Faithfully,

Jason Heng
Claims Director

7 Days.
part by part.
before part photos.
Gm. Ramp - 82880282
8/7/22
Not Authorized.
Excess : \$ 2000.