

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 **FAX:** 68357416
ATTN: Motor Claim Department

Estimate No: EST2200213
Date: 06 Jul 2022
Veh Reg No: SFH3607S
Make/Model: MAZDA 6 4 DOOR
SEDAN 2.0L SP 6EAT
Chasis No: JM6GJ1072G0237847
Reg. Date: 30/05/2016
Your Ref No: GBL4451T

Claim Type: Third Party
Accident Date: 04/07/2022
TP Veh Reg No: GBL4451T

Estimate Repair Cost to Vehicle No :SFH3607S

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
	List Price		
1	1 PC REAR BUMPER	1,381.50	
2	1 PC REAR BUMPER SIDE RETAINER LH	71.00	
3	1 PC TAIL LAMP - LH	1,692.30	
		3,144.80	
	Less 20%	628.96	2,515.84
	Special Net		
4	1 SET REAR BUMPER CLIPS	60.00	
5	1 SET REAR FENDER TRIM CLIPS LH	60.00	
		120.00	120.00
	Labour		
6	1 TO CHECK WIRING	50.00	
7	1 TO REMOVE AND REFIT REVERSE SENSOR	80.00	
8	1 TO REMOVE AND REFIT REAR INNER TRIM	80.00	
9	1 TO SPRAY UNDERSEAL	80.00	
10	1 (REAR) TO SPRAY PAINTING	700.00	
11	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	700.00	
		1,690.00	1,690.00

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 **FAX:** 68357416
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 04/07/2022
TP Veh Reg No: GBL4451T

Estimate No: EST2200213
Date: 06 Jul 2022
Veh Reg No: SFH3607S
Make/Model: MAZDA 6 4 DOOR
SEDAN 2.0L SP 6EAT
Chasis No: JM6GJ1072G0237847
Reg. Date: 30/05/2016
Your Ref No: GBL4451T

Estimate Repair Cost to Vehicle No :SFH3607S

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
	Total		S\$ 4,325.84
	Add GST @ 7%		302.81
	Total Amount Payable		<u><u>S\$ 4,628.65</u></u>

TOTAL: SINGAPORE DOLLAR FOUR THOUSAND SIX HUNDRED TWENTY EIGHT AND CENTS SIXTY FIVE ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd



AUTHORISED SIGNATURE