

金興(嬰)汽車私人有限公司

K. KIM HIN AUTO PTE LTD

160 Sin Ming Drive #02-18/19/20

Sin Ming AutoCity

Singapore 575722

Tel: 6452 7018 (5 Lines) Fax: 6458 3895

Your Reference : GA567298
Accident Date : 29-Jun-2022

Our Ref : 022130 / CARIN

AXA INSURANCE PTE LTD
ROBINSON ROAD
P.O BOX 1094
Singapore 902144

No. : 32440

Date : 04-Jul-2022

PAGE : 1

ESTIMATED COST OF REPAIR FOR TOYOTA PRADO 2.7TX A (2010) SBH1888H
=====

1 pc front bumper
2 pcs front bumper side retainer
LH/RH
1 pc front bumper centre beam
2 pcs front bumper side beam LH/RH
10 pcs front bumper clips
1 pc front bumper lower centre
grille
1 pc front bumper lower cover
1 pc front bumper sponge
1 pc front bumper reinforcement
2 pcs front bumper reinforcement
bracket LH/RH
2 pcs front bumper foglamp LH/RH
2 pcs front bumper foglamp cover
LH/RH
1 pc front bumper parking sensor
1 pc front grille
2 pcs front grille top bracket LH/RH
10 pcs front grille clip
1 pc front grille logo
1 pc bonnet
1 pc bonnet outer chrome
1 pc bonnet inner seal
1 pc bonnet insulator
11 pcs bonnet insulator clip
2 pcs bonnet hinge LH/RH
1 pc bonnet lock
1 pc bonnet lock cover

Con't Page 2 ...

金興(龔)汽車私人有限公司
K. KIM HIN AUTO PTE LTD
 160 Sin Ming Drive #02-18/19/20
 Sin Ming AutoCity
 Singapore 575722
 Tel: 6452 7018 (5 Lines) Fax: 6458 3895

Your Reference : GA567298
 Our Ref : 022130

Page : 2
 No. : 32440

1 pc bonnet pull lock cable
 1 pc bonnet pull lock cable cover
 1 pc front support panel
 2 pcs front support panel air guide
 LH/RH
 1 pc front support panel top
 garnish
 10 pcs front support panel top
 garnish clip
 1 pc front brace panel
 2 pcs headlamp assy LH/RH
 1 pc aircon condenser
 1 pc aircon condenser liquid pipe
 1 pc aircon condenser discharge
 pipe
 2 pcs horn LH/RH
 1 pc steering airbag
 1 pc steering clock spring
 1 pc driver knee airbag
 1 pc front passenger airbag
 1 pc dashboard
 2 pcs front airbag sensor
 1 pc airbag control unit
 2 pcs front seat belt LH/RH
 2 pcs front seat belt buckle LH/RH

	-----	0.00	
Add 10% :		0.00	
	-----		0.00

1 pc front number plate

To remove, cut out damaged parts,
 panel beating, welding, align,
 refix and to renew affected parts.

Con't Page 3 ...

金興(龔)汽車私人有限公司

K. KIM HIN AUTO PTE LTD

160 Sin Ming Drive #02-18/19/20

Sin Ming AutoCity

Singapore 575722

Tel: 6452 7018 (5 Lines) Fax: 6458 3895

Your Reference : GA567298

Our Ref : 022130

Page : 3

No. : 32440

To focus headlamps. To check front wiring and lighting operation.

To remove aircon condenser, pipes and driers. Vacuum and recharge gas

To remove and renew front instrument panel assy, to rewiring and transfer instrument fittings.

To remove and renew air bag sensors seat belts assy, to rewiring and re-setting program

To putty and respray on affected portions.

Total : -----
 S\$ 0.00
 =====