

Company Reg No: 202136905K

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowork@gmail.com



DATE : 06.07.2022

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
VEHICLE NO : SMR6626G
MODEL : HYUNDAI AVANTE
DATE OF ACCIDENT : 06.07.2022
TIME OF ACCIDENT : 08:50HRS

DEPTS
KM110841CMLU029557
Xiao Tong.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>delid</i>	1	\$ 459.40	\$ 459.40
2	REAR BUMPER LAMP <i>canled</i>	2	\$ 201.50	\$ 403.00
3	REAR BUMPER LAMP WIRE HARNESS <i>new</i>	1	\$ 121.00	\$ 121.00
4	REAR BUMPER NUMBER PLATE LAMP <i>new canled</i>	2	\$ 28.00	\$ 56.00
5	REAR BUMPER CENTRE (BLACK) <i>delid</i>	1	\$ 353.50	\$ 353.50
6	REAR BUMPER RETAINER <i>new</i>	2	\$ 29.40	\$ 58.80
7	REAR BUMPER REINFORCEMENT <i>canled</i>	1	\$ 294.80	\$ 294.80
8	REAR BUMPER REINFORCEMENT BRACKET <i>new</i>	2	\$ 5.00	\$ 10.00
9	REAR BUMPER BRACKET <i>new</i>	5	\$ 78.60	\$ 393.00
10	REAR BUMPER SIDE INNER LOWER GARNISH <i>new</i>	2	\$ 37.20	\$ 74.40
11	REAR FENDER INNER COWLING (REAR) <i>new</i>	2	\$ 60.00	\$ 120.00
12	REAR FENDER INNER TRIM <i>new</i>	2	\$ 208.00	\$ 416.00
13	TAILLAMP <i>canled</i>	2	\$ 1,052.10	\$ 2,104.20
14	BOOTLID <i>Buckled</i>	1	\$ 1,782.40	\$ 1,782.40
15	BOOTLID LAMP <i>new</i>	2	\$ 664.20	\$ 1,328.40
16	BOOTLID LOGO <i>new</i>	1	\$ 54.70	\$ 54.70
17	BOOTLID EMBLEM 'AVANTE' <i>new</i>	1	\$ 31.20	\$ 31.20
18	BOOTLID EMBLEM 'S' <i>new</i>	1	\$ 63.90	\$ 63.90
19	BOOTLID OUTER SWITCH BUTTON <i>new</i>	1	\$ 196.20	\$ 196.20
20	BOOTLID DETECTOR (OUTER) <i>canled</i>	1	\$ 369.70	\$ 369.70
21	BOOTLID DETECTOR (INNER) <i>new canled</i>	1	\$ 358.60	\$ 358.60
22	BOOTLID DETECTOR WIRE HARNESS <i>new</i>	1	\$ 426.70	\$ 426.70
23	BOOTLID REVERSE CAMERA <i>new</i>	1	\$ 826.10	\$ 826.10
24	BOOTLID HINGE <i>new</i>	2	\$ 94.30	\$ 188.60

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
 VEHICLE NO : SMR6626G
 MODEL : HYUNDAI AVANTE
 DATE OF ACCIDENT : 06.07.2022
 TIME OF ACCIDENT : 08:50HRS

25	BOOTLID STOPPER <i>Not m</i>	2	\$ 7.00	\$ 14.00	x
26	BOOTLID TOP LOCK <i>Dmgd.</i>	1	\$ 116.20	\$ 116.20	✓
27	BOOTLID LOWER LOCK <i>Not m</i>	1	\$ 16.00	\$ 16.00	x.
28	BOOTLID WEATHER STRIP <i>Lot</i>	1	\$ 92.50	\$ 92.50	✓
29	REAR END PANEL <i>Dented</i>	1	\$ 454.60	\$ 454.60	✓
30	REAR END PANEL TOP GARNISH <i>Repld</i>	1	\$ 59.80	\$ 59.80	✓
31	REAR FLOOR PANEL <i>Ryis</i>	1	\$ 246.50	\$ 246.50	x
32	REAR FLOOR PANEL TOP BOARD <i>Repld</i>	1	\$ 219.10	\$ 219.10	✓
33	REAR TOOLS SPONGE <i>Not m</i>	1	\$ 164.90	\$ 164.90	x
34	REAR SPARE TYRE BOLT <i>Not m</i>	1	\$ 12.00	\$ 12.00	x.

7084.50 TOTAL PRICE \$ 11,886.20
 5667.60 LESS 20% \$ 2,377.24
 SUB TOTAL PRICE \$ 9,508.96

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>Dented.</i>	1	\$ 80.00	\$ 80.00	50.
2	REAR BUMPER CLIP (SET) <i>New</i>	1	\$ 80.00	\$ 80.00	30.
3	REAR BUMPER SIDE INNER LOWER GARNISH CLIP (SET) <i>New</i>	1	\$ 80.00	\$ 80.00	20
4	BOOT LID INSULATOR CLIP (SET) <i>Not m</i>	1	\$ 80.00	\$ 80.00	x.
5	TAIL LAMP CLIP (SET) <i>New</i>	1	\$ 60.00	\$ 60.00	20.
6	REAR FENDER INNER COWLING CLIP (SET) <i>Not m</i>	1	\$ 80.00	\$ 80.00	x.
7	REAR FENDER INNER TRIM CLIPS (SET) <i>Not m</i>	1	\$ 80.00	\$ 80.00	x.
8	REAR END PANEL TOP GARNISH CLIP (SET) <i>New</i>	1	\$ 40.00	\$ 40.00	10.
9	REAR END PANEL INSULATION SEALANT <i>New</i>	1	\$ 150.00	\$ 150.00	60
10	REAR FLOOR PANEL INSULATION SEAL <i>Not m</i>	1	\$ 350.00	\$ 350.00	x.
11	REVERSE SENSOR <i>Damaged</i>	1	\$ 220.00	\$ 220.00	200

380 TOTAL \$ 1,300.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 2,000.00	800
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,800.00	800
3	TUFF COAT	\$ 250.00	60
4	WIRING CHECK	\$ 180.00	30

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
 VEHICLE NO : SMR6626G
 MODEL : HYUNDAI AVANTE
 DATE OF ACCIDENT : 06.07.2022
 TIME OF ACCIDENT : 08:50HRS

5	REMOVE AND REFIX UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$ 350.00	80
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
7	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	50
8	REAR CHASSIS ALIGNMENT	\$ 250.00	x
9	CONDUCT WATER LEAKAGE TEST	\$ 120.00	x.
10	TRANSFER BOOTLID MECHANISM	\$ 80.00	60 ✓
11	REMOVE AND REFIX FUEL TANK TO FACILITATE FLOOR PANEL REPLACEMENT	\$ 80.00	x
12	REMOVE AND REFIX REAR EXHAUST PIPE	\$ 180.00	+
13	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 250.00	x

TOTAL \$ 5,700.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 10,808.96
 TOTAL LABOUR COST : \$ 5,700.00
 TOTAL REPAIR COST : \$ 16,508.96

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP : 8297 9787

Adrian Lj
 1/5 07/07/22.
 06 days

total: 8017.60

1/5: 6.4K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

6.4K

1950