

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER: India International Insurance Pte Ltd (HQ)
CTPL

Singapore

MVA : Loke Wei Yang

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	03/07/2022
Vehicle Reg. No.:	SHC1505T	Driveable?	
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Vehicle Reg. Date:	14/11/2019
Vehicle Colour:	BLUE	Chassis No:	KMHC851CVLU189038
Engine No:	G4LEKU405596		
Odometer:	249459 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	6		
Remarks:	TEL: 62148355		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS

	Amount
Parts	8,949.32
Miscellaneous Items	11.00
Labour	2,710.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$)	11,670.32
+ GST 7.00% (\$)	816.92
Nett Amount (\$)	12,487.24

This claim is handled by: MS. LOKE YY

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 04 Jul 2022)

Parts: 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SHC1505T/04/07/2022 13:38

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT BUMPER COVER	20.00	0.00	Rx *481.10 FL
2	1		*FRT BUMPER CLIPS	20.00	0.00	na ✓ *22.00 FL
3	1		*FRT BUMPER SIDE BRACKET LH	20.00	0.00	X *28.00 FL
4	1		*FRT BUMPER CENTRE MOULDING UPPER	20.00	0.00	out ✓ *368.50 FL
5	1		*HEADLAMP LH	20.00	0.00	X *2,110.30 FL
6	1		*FRT BUMPER SIDE MOULDING LH	20.00	0.00	X *93.45 FL
7	1		*DAY LIGHT LH	20.00	0.00	X *642.50 FL
8	1		*REAR BUMPER COVER	20.00	0.00	de ✓ *459.40 FL
9	1		*REAR BUMPER CLIPS	20.00	0.00	ner ✓ *22.00 FL
10	1		*REAR BUMPER CENTRE MOULDING ASSY	20.00	0.00	de ✓ *451.25 FL
11	1		*REAR BUMPER REINFORCEMENT	20.00	0.00	? *394.80 FL
12	1		*REAR BUMPER REINFORCEMENT BRACKET LH	20.00	0.00	? *138.10 FL
13	1		*REAR BUMPER REINFORCEMENT BRACKET RH	20.00	0.00	? *138.10 FL
14	1		*REAR BUMPER FOG LAMP	20.00	0.00	X *201.50 FL
15	1		*REAR BUMPER LICENCE LAMP	20.00	0.00	X *85.30 FL
16	1		*ANTENNA ASSY SMARTKEY	20.00	0.00	? *40.50 FL
17	1		*REAR BUMPER SIDE BRACKET LH	20.00	0.00	? *55.80 FL
18	1		*REAR BUMPER SIDE BRACKET RH	20.00	0.00	X *55.80 FL
19	1		*REAR BUMPER LOWER CTR MOULDING	20.00	0.00	? *155.00 FL
20	1		*BOOTLID HYUNDAI PLATE	20.00	0.00	na X *24.30 FL
21	1		*EMBLEM HYBRID	20.00	0.00	na X *24.30 FL
22	1		*EMBLEM - IONIQ	20.00	0.00	na X *31.30 FL
23	1		*BOOTLID	20.00	0.00	na X *2,549.70 FLX
24	1		*REAR FENDER ADVERTISEMENT STICKER LH	0.00	0.00	na ✓ *100.00 F
25	1		*REAR FENDER ADVERTISEMENT STICKER RH	0.00	0.00	na ✓ *100.00 F
26	1		*BOOTLID ADVERTISEMENT STICKER	0.00	0.00	X *100.00 F
27	1		*REAR NUMBER PLATE WITH TRIM COVER	0.00	0.00	na ✓ *55.00 F
28	1		*BOOTLID COMFORT TEL NO STICKER	0.00	0.00	na X *40.00 F
29	1		*BOOTLID COMFORT LOGO STICKER	0.00	0.00	na X *30.00 F
30	1		*BOOTLID COMFORT APP STICKER	0.00	0.00	na X *30.00 F
31	1		*REAR BUMPER REVERSE SENSOR	0.00	0.00	na ✓ *180.00 F
32	1		*TAIL LAMP LH	20.00	0.00	X *935.40 FL
33	1		*BOOT LID LAMP LH	20.00	0.00	X *822.00 FL
34	1		*REAR BUMPER ADVERTISEMENT STICKER	0.00	0.00	na ✓ *50.00 F

F=Franchise part. L=ListItemDisc.

Sub Total (\$)

11,015.40

- List Item Discount on L Items (\$)

2,066.08

Total Parts (\$)

8,949.32

ComfortDelGro Engineering Pte Ltd/SHC1505T/04/07/2022 13:38. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New 525	1,600.00
2	SPRAY PAINTING CHARGE	New 500	850.00
3	CHK ALL LIGHTING	New 80	120.00
4	REMOVE/REFIX REVERSE SENSOR	New 30	80.00
5	TUFF KOTE	New x	60.00
Gross Labour Cost (S\$)			2,710.00

ComfortDelGro Engineering Pte Ltd/SHC1505T/04/07/2022 13:38. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tanpin 9749 3749
 'wp' 6/7/22 @ 430pm
 p/p Resurvey before paint
 tanpin @ 16hantab.com
 03 days

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 04.07.2022 12:34

Page : 1

am: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 4353657

JC NO 305521885

FROMER
AS COMFORT TRANSPORTATION PTE LTD
FROMER NO. 7010045
RESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
(R) 65508755 (O)
(P)

REGN NO. SHC1505T	MILEAGE
MAKE HYUNDAI	FUEL E.....1/2.....F
MODEL IONIQ(G3)	DATE/TIME IN 04.07.2022 08:30
YR OF MANU. 14.11.2019	TARGET DATE
CHASSIS CODE KMHC851CVLU189038	COMPLETION DATE/TIME


OUNT CARD NO.

JOB DESCRIPTION

ccident Date: 03.07.2022
ATURE: 3P 03.07.2022

/NO LABOR CODE

DESCRIPTION



ICKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

ledgement Slip

Exit Pass

Vo.: SHC1505T YY

Vehicle No.: SHC1505T

Service Advisor

Signature/Date

Name of Service Advisor

Date

turned to Service Reception upon collection

To be kept by Security Guard